




EPA Region 5 Records Ctr.



235993

March 21, 2002  
FLKE-005

PHONE  
630-293-6330

**VIA FIRST CLASS MAIL**

Mr. Fred Micke  
U.S. EPA, Region 5  
On-Scene Coordinator  
Emergency Response Section #3  
77 W. Jackson Blvd. (SE-5J)  
Chicago, Illinois 60604-3590

SUBJECT: Response to USEPA Comments Dated 03/06/02 re: Investigation Work Plan

REFERENCE: DuSable Park, Chicago, IL

Dear Mr. Micke:

Thank you for reviewing Kerr-McGee's revised Investigation Work Plan for the proposed limited site investigation at the DuSable Park Site in Chicago, IL. The original plan Work Plan was submitted to U.S. EPA on 11/12/01 and comments were received on 1/29/02. The Work Plan was revised and resubmitted to U.S. EPA on 2/12/02 and comments were received on 3/6/02. In response to your 3/6/02 comments, Kerr-McGee has prepared this response letter and attached a revised Investigation Work Plan for your review and approval.

Kerr-McGee is ready to begin the limited site Investigation pending your approval of the attached Work Plan.

The following is a recitation of the EPA comments, individually followed by Kerr-McGee's responses:

**USEPA Comment # 1**

**Sampling Methods, 7.2.4, page 5 of 8 --USEPA and Field Investigation Leader must agree to alternative methods in the Investigation Work Plan that are not part of the finalized Workplan.**

**Kerr-McGee Response**

Section 7.2.4 of the Soil Sampling Work Instruction has been modified to include the referenced text.

**USEPA Comment # 2**

**Surveys for Surface Contamination and Release of Equipment for Unrestricted Use, Section 3.2 and Attachment 3; Decontamination, Section 3.2** – USEPA has required that Federal criteria and guidelines be followed unless State criteria and guidelines be followed unless State criteria and guidelines are more restrictive. USEPA relies upon guidelines used by the Nuclear Regulatory Commission for unrestricted release of objects as found in Table 1 of Regulatory Guide 1.86.

Section 3.2 Guidelines [also shown on page 13 of 17, Attachment 3, WCP 345-5] exceed the guidelines in the Nuclear Regulatory Commission's Regulatory Guide 1.86. For removable radium contamination (radium-226, radium-28) this is 20 disintegrations per minute per 100 square centimeters (dpm/100 cm<sup>2</sup>). Where contamination is removable plus fixed the levels are 100 dpm/100 cm<sup>2</sup> (average) and 300 dpm/100 cm<sup>2</sup>.

A copy of Regulatory Guide 1.86 is attached.

Kerr-McGee Response

The comments reference Kerr-McGee's West Chicago Project Standard Operating Procedures (SOPs) that have been approved for use by the Illinois Department of Nuclear Safety. Due to the limited extent of this investigation, it is more appropriate to create Work Instructions to address these comments rather than revising approved SOPs. Therefore SOPs 345 (Surveys for Surface Contamination and Release of Equipment for Unrestricted Use) and 347 (Decontamination) have been eliminated and replaced with the corresponding Work Instructions.

These new Work Instructions reference the June 1974 U.S. Atomic Energy Commission Regulatory Guide that USEPA included with their 3/6/02 comments.

Please call me at (630) 293-6374 if you have any questions.

Very truly yours,

KERR-McGEE CHEMICAL LLC

A handwritten signature in cursive script that reads "Bernard Bono".

Bernard Bono  
Senior Engineer

Attachments

cc: Mary L. Fulghum, Esq. (USEPA)

File: DPCH – EPA

# **INVESTIGATION WORK PLAN**

**DUSABLE PARK SITE**

**CHICAGO, ILLINOIS**

**KERR-MCGEE CHEMICAL LLC**

**November 12, 2001**

*Revised February 12, 2002*

*Revised March 21, 2002*

## TABLE OF CONTENTS

<b>SCOPE AND OBJECTIVES .....</b>	<b>1</b>
<b>REPORTING .....</b>	<b>2</b>
<b>ACCESS .....</b>	<b>2</b>
<b>UTILITIES .....</b>	<b>2</b>
<b>DESCRIPTION OF CREW ....</b>	<b>2</b>
<b>HEALTH AND SAFETY .....</b>	<b>2</b>

## LIST OF FIGURES

Figure 1	Site Location Map .....	4
Figure 2	Four Investigation Areas .....	5
Figure 3	Environmental Access Agreement .....	6

## WORK INSTRUCTIONS

Surface Gamma Survey  
Soil Sampling  
Sample Preparation  
Downhole Gamma Logging  
**Surveys for Unrestricted Release of Equipment**  
**Decontamination**

## STANDARD OPERATING PROCEDURES

<del>SOP WCP 345</del>	<del>Surveys for Surface Contamination and Release of Equipment for Unrestricted Use</del>
<del>SOP WCP 347</del>	<del>Decontamination</del>
SOP WCP 363	Operation and Calibration of the Canberra HPGe Gamma Detector
SOP WCP 365	Moisture Analysis
SOP WCP 376	Portable Survey Instrument Operability Checks
SOP WCP 379	Calibration of the Ludlum Scaler Ratemeter Model 2221

## SCOPE AND OBJECTIVES

This Investigation Work Plan provides an overview of work that will be done to determine whether the four anomalies located by the U.S. EPA represent buried thorium residuals or surface concentration anomalies. The work will be performed at the DuSable Park Site (Site) located in Chicago, Illinois. The location of the Site is shown on Figure 1. The Site is currently a vacant parcel heavily overgrown with tall weeds and scrub trees.

Kerr-McGee Chemical LLC (Kerr-McGee) is performing this limited Site investigation. Kerr-McGee, through its own personnel and qualified contractors, will investigate four specific areas of the Site, previously identified by the U.S. EPA as having surface gamma readings above background levels. These four areas are shown on Figure 2.

The Investigation Work Plan describes the work to be performed, health and safety issues, and includes the Work Instructions and Standard Operating procedures (SOPs) to be used. The Work Instructions to be used include surface gamma survey, soil sampling, sample preparation, and downhole gamma logging, **surveys for unrestricted release of equipment and decontamination**. The standard operating procedures that will be used include ~~Decontamination~~ (SOP 347), Operation of the Canberra HPGe Gamma Detector (SOP 363) and Moisture Analysis (SOP 365).

The four investigation areas will be located in the field using a Trimble Pro-XR global positioning system (GPS) unit with a datalogger. This unit will record the northings and eastings of the boreholes to a horizontal accuracy of +/- one meter. These four areas will be surface gamma surveyed to find the surface area with the highest gamma reading. At the point of the highest surface gamma reading in each area, a borehole will be advanced vertically downward by hand pounding a geoprobe tube down to a depth of two feet. The boreholes will then be gamma logged with a calibrated meter to determine if low-level 11(e)(2) byproduct material is present in concentrations exceeding 7.1 pCi/g. All surface gamma survey and downhole gamma logging readings will be collected as quality data.

If the gamma logging count rates do not increase with depth, then the surface activity does not represent buried material. If count rates do increase, the hole could be advanced to refusal to determine the thickness and activity of the substrata material exceeding the cleanup criteria. If material exceeding the cleanup criteria is encountered at depth, up to four step out holes may be performed at each location to collect additional information regarding the horizontal extent. Additional investigation beyond the above-described stepouts would change the current scope of this investigation and would require a revision to this Investigation Work Plan.

Soil samples will be collected using a hand auger in accordance with the attached soil sampling Work Instruction. The soil sample will be collected at a depth corresponding to the interval 3" above to 3" below the highest downhole gamma reading. Samples will be homogenized in the field and rocks, sticks and foreign objects greater than approximately one-inch will be removed. The field sample will then be split with the U.S. EPA who may then choose to do additional screening and homogenizing in the field.

The samples will be prepared in the lab in accordance with the sample preparation Work

Instruction, moisture corrected in accordance with SOP 365, and analyzed for the U-238, Th 232 & U-235 decay series using the Canberra HPGe Gamma Detector in accordance with SOP 363.

## **REPORTING**

A report of the investigation results will be submitted to the U.S. EPA within 60 days after the borings are completed. The report will include a map of anomaly areas showing the borehole locations, surface gamma readings, downhole gamma logs and soil sample results. The soil sample results will include radionuclide identities, activity concentrations and the depths below surface of the samples.

## **ACCESS**

The Kerr-McGee Field Investigation Leader will obtain access to the land parcels comprising the Site from the respective property owner (Chicago Park District) prior to beginning investigative activities. This access will include permission for Kerr-McGee and U.S. EPA employees, contractors, agents, consultants, designees, and representatives to conduct actions required as part of this investigation. The Environmental Access Agreement form has been included as Figure 3. Kerr-McGee will provide the U.S.EPA with a minimum of two business days notice prior to the start of the limited Site investigation.

## **UTILITIES**

Utilities will be located prior to performing any ground intrusive activity on the property. The Field Investigation Leader will be responsible for originating a request for a DIGGER Utility Locate for each property where drilling is proposed. The phone number for DIGGER is 1-312-744-7000. DIGGER clearances are valid for fourteen days.

## **DESCRIPTION OF CREW**

Delineation drilling boreholes will be advanced by hand pounding the geoprobe pipe using a heavy weight. The crew typically consists of a driller and a helper to advance the borings. In addition, a Health Physics (HP) technician will be present to perform the surface gamma survey, downhole gamma logging, soil sampling and decontamination tasks. A Kerr-McGee Field Investigation Leader will also be on site to oversee the work.

## **HEALTH AND SAFETY**

The Field Investigation Leader will ensure all work is done in a safe and proper manner. A brief tailgate meeting will be conducted on site before initiating work to explain potential hazards that may be encountered during the work. Potential hazards which could be encountered during investigation activities include contaminated soil materials, contact with trespassers sleeping in the weeds, hazards associated with lifting and hand-pounding holes, contact with utilities, and contact with wild parsnip.

Constituents of concern that could be encountered during investigation activities include low-level 11(e)(2) byproduct material present in concentrations exceeding the action criteria. This may include U-238, Th-232 and progeny. U-235 would be expected to be present in a ratio of 0.0456 times the activity of U-238.

The mechanisms for exposure for these materials are direct exposure, inhalation, ingestion, and eye/skin contact. The primary mechanism for exposure is direct exposure to external gamma radiation. All workers will be instructed in appropriate safety measures to protect against exposure to the above materials.

Trespassers shall be addressed in a courteous and professional manner, however if they become hostile or aggressive, the crew will vacate the work area and call the Chicago Police Department for assistance.

The site is heavily covered with wild parsnip, which can be a strong skin irritant on sunny days. The crew will be instructed to wear long sleeve shirts and gloves at all times they are working in the tall weeds area.

It is anticipated that the investigation work can be done in Modified Level D PPE. Modified Level D PPE for the project includes steel toed or OSHA approved safety work boots or shoes, disposable work gloves, and safety glasses. All visitors must have appropriate PPE and must be accompanied by the Field Investigation Leader.

If monitoring indicates that contamination is present at the surface, above action criteria levels of 7.1 pCi/g, then a restricted access area will be created at the perimeter of known contamination, with an appropriate buffer. If work must be performed in an area with surface contamination above action criteria levels, then the senior HP technician will upgrade the PPE requirements to include disposable coveralls, rubber booties and cotton gloves. Any upgrades in PPE will be at the discretion of the attending HP and will be based on the activity of the material encountered and the task being performed.

All workers and visitors will follow decontamination procedures in accordance with ~~SOP 347~~ and with ~~Nuclear Regulatory~~ **Atomic Energy Commission** levels in Regulatory Guide 1.86, **Table 1** and, only if more restrictive, to State of Illinois regulatory levels if they come into contact with low-level 11(e)(2) byproduct material in concentrations exceeding the action criteria. Before leaving the exclusion zone, site personnel shall be checked through use of a hand-held frisker to ensure that contamination is not present on skin or clothes.





DuSable Park Survey - Chicago, IL

DATE

SHEET

W.O. NO./A.F.E. NO.

PREPARED BY

CHECKED BY




FIGURE 2 -  
FOUR INVESTIGATION AREAS

## ENVIRONMENTAL ACCESS AGREEMENT

1. I (we), the undersigned, do hereby grant to Kerr-McGee Chemical LLC ("Kerr-McGee"), its employees, authorized representatives and contractors; United States Environmental Protection Agency ("U.S. EPA"), its representatives and contractors; license and permission to enter upon owner's property described as:

Property Address/Location:

for the purpose of conducting environmental investigation activities. Kerr-McGee is not U.S. EPA's representative with respect to liability associated with the Chicago Streeterville Area Projects.

2. Upon conclusion of the investigation activities, Kerr-McGee shall remove all its equipment, and disturbed areas shall be restored, to the extent practical, to original conditions.

Dated this \_\_\_\_\_ day of \_\_\_\_\_, 2002.

Phone#

Owner(s):

---

---

---

---

File: DPCH-

# **DuSable Park**

## **Surface Gamma Survey Work Instruction**

**Date:** February 6, 2002

---

### **1. PURPOSE**

This work instruction provides direction for surface gamma radiological survey work to be performed for the limited site investigation at DuSable Park in Chicago, Illinois.

### **2. SCOPE**

Radiological surveys will be performed at the Site as part of the limited Site investigation

### **3. REFERENCES**

- 3.1 REF Facility Procedure - SOP-WCP 376 "Portable Survey Instrument Operability Checks"
- 3.2 REF Facility Procedure - SOP-WCP 379 "Calibration of the Ludlum Scaler Ratemeter Model 2221."

### **4. EQUIPMENT AND MATERIALS**

The following equipment may be used as part of the survey programs. Other equipment may be substituted if necessary because of availability of the items listed or the conditions encountered at the site.

- 4.1 Trimble Pro XR GPS unit with a datalogger to record the northing, easting and count rate of each surface gamma survey point.
- 4.2 2-inch by 2-inch NaI (T1) gamma detector.
- 4.3 Ludlum Model 2221 portable scaler ratemeter analyzer.
- 4.4 Weedwacker (if necessary).

## **5. INSTRUCTIONS FOR RADIOLOGICAL SURVEY**

- 5.1 Navigate to EPA anomaly areas using GPS unit.
- 5.2 Clear brush for gamma survey walkover survey.
- 5.3 Locate point of highest surface gamma reading in each of the four anomaly areas.
- 5.4 The Ludlum ratemeter is set for 2-second time-weighted average count rate.
- 5.5 Hold the survey meter probe perpendicular to the ground surface at a height of approximately two to six inches.
- 5.6 Walk along back and forth over the survey area on one-meter grid lines at a maximum speed of about 0.5 meters per second (1 mile per hour).
- 5.7 Continue surveying for a minimum ten-meter radius or until readings approach background around the highest reading in each area

## **6. RECORDS/REPORTS/NOTIFICATIONS**

The following documents will be maintained as quality records:

- Field Logbooks
- Map of gamma survey locations
- Data downloads from GPS unit data logger

# **DuSable Park**

## **Soil Sampling Work Instruction**

**Date:** March 19, 2002

---

### **1. PURPOSE**

This work instruction provides direction for collecting soil samples and splitting them with the U.S. EPA as part of the limited site investigation at DuSable Park in Chicago, Illinois. Kerr-McGee's split samples will be submitted to Kerr-McGee's laboratory for counting in a one-liter Marinelli geometry. The samples will be moisture corrected and analyzed for the U-238, Th-232 & U-235 decay series using the Canberra HPGe Gamma Detector.

### **2. SCOPE**

The DuSable Park samples will be collected from the area with the highest surface gamma survey reading in each of the four anomaly areas identified by the U.S. EPA. The Field Investigation Leader will coordinate the sampling efforts.

### **3. REFERENCES**

- 3.1 Surface Gamma Survey Work Instruction for DuSable Park
- 3.2 U.S. Nuclear Regulatory Commission, NUREG/CR-5849, Manual for Conducting Radiological Surveys in Support of License Termination, June 1992.

### **4. EQUIPMENT AND MATERIALS**

#### **4.1 Equipment and Materials Management**

Downhole and sampling tools are cleaned in accordance with the Decontamination Procedure (SOP-WCP347).

#### **4.2 Sampling Equipment and Materials**

Equipment used for soil sampling includes the following:

- Auger or other Coring Tool

- Shovel and Trowel
- Plastic Collection Bags
- Plastic Sheets (optional)
- Sampling Tracking Form
- Field Logbook
- Container (for collecting potentially contaminated waste generated during the sampling process ) (e.g., gloves, plastic sheets, etc.)
- Bucket or stainless steel mixing bowl (for homogenizing samples)
- Appropriate Personal Protective Equipment
- Paper Towels for decontamination
- Survey Instrument (for verifying clean sampling equipment and hands)

Other equipment may be substituted if necessary because of availability of the items listed or the conditions encountered at the site. Substitute equipment shall be documented in the Field Logbook and approved by the Field Investigation Leader.

## **5. IN-SITU SOIL SAMPLING**

This section describes the methods for choosing sample locations and sampling methods.

### **5.1 Sample Location Selection**

The soil sample will be collected at a depth corresponding to the interval 3" above to 3" below the highest downhole gamma reading

### **5.2 Drilling Procedures**

In general, manual or power-auger assisted drilling will be used. Drilling will follow the procedures described in Section 7.2.

## **6. SAMPLE TRACKING**

To establish the documentation necessary to track the sample from the time of collection, the sample identification and Sample Tracking Forms must accompany samples that are sent to the laboratory. If potential contamination is indicated (material history, etc.) the outside of the sample container will be screened for loose contamination.

## **7. SAMPLING METHODS**

### **7.1 Surface Soil Sampling**

- 7.1.1 If necessary, to minimize contamination, spread a clean sheet of plastic next to the area to be sampled; assemble the sampling equipment required.
- 7.1.2 Enter the complete information on the Sample Tracking Form:
  - Sample Number
  - Sample Matrix
  - Sample Location
  - Purpose of Sample Collection
  - Include applicable comments regarding the sample, location, weather, conditions, or other factors that may be relevant
  - Collected by (your name).
- 7.1.3 Mark the collection bag or prepare the identification tag for the sample.
- 7.1.4 Collect the soil samples from the six-inch interval corresponding to the depth of the highest downhole gamma log reading. Use a shovel or trowel to collect soil from the depth required.
- 7.1.5 If the soil sample is taken from the uppermost six-inch layer at the surface, the top three inches of soil must not be discarded. This should include the dirt around the grass and plants.
- 7.1.6 Place the representative soil sample in containers and stir to ensure homogeneity and sample uniformity, if necessary. Remove rocks, sticks, and foreign objects greater than approximately one (1) inch. A one-inch sieve can be used if necessary.
- 7.1.7 Split the sample with the U.S. EPA.
- 7.1.8 Attach the identification tag to the sample bag if appropriate and place the bag in the sample container.
- 7.1.9 Decontaminate the sampling equipment as required by Section 8.
- 7.1.10 Return any location markers (such as pin flags) that were removed in order to sample. Fill in all sampling holes to eliminate a possible tripping hazard.

7.1.11 If specific data are not available, mark a pin flag with the sample identification number and place the flag at the center of the sampling location before leaving.

## 7.2 Subsurface Sampling (Undisturbed Soils)

7.2.1 If necessary, to minimize contamination, spread a clean sheet of plastic next to the area to be sampled; assemble the sampling equipment required.

7.2.2 Enter the complete information on the Sample Tracking Form:

- Sample Number
- Sample Matrix (i.e., substance)
- Sample Location
- Purpose of Sample Collection
- Include applicable comments regarding the sample, location, weather, conditions, or other factors that may be relevant
- Collected by (your name)

7.2.3 Mark the collection bag or prepare the identification tag for the sample.

7.2.4 Sample the material using a hand core sampling tool or hammer driven split spoon sampler. Collect the soil samples from the six-inch interval corresponding to the depth of the highest downhole gamma log reading. Use a shovel or trowel to collect soil from the depth required. Alternatively, an auger method may be used.

Using an auger, drill to the desired sampling depth; keep the auger turning until no more material comes up. The soil around the hole is fairly well mixed and representative of the interval just drilled. Origin surface material adjacent to or far away from the hole will not be part of the sample.

If the soil sample is to be obtained from a particular depth (not a composite from surface to depth), and the material refuses to pass into the coring tool, the following sampling method will be performed. Drill to the top of the desired sampling depth; keep the auger turning until no more material comes up. Remove the auger and sample the material using a hand core sampling tool or hammer driven split spoon sampler. The first three inches of the sampled obtained in this particular instance will be considered slough and not part of the desired sample.



NOTE: If, due to the conditions of the sampling area, this method does not work, an alternative method(s), approved by the Field Investigation Leader, **and agreed to by the USEPA**, may be used. Alternative methods, when used, will be documented by the field personnel in the Field

- 7.2.5 If the soil sample is taken from the uppermost six-inch layer at the surface, the top three inches of soil must not be discarded. This should include the dirt around the grass and plants.
- 7.2.6 Place the representative soil sample in containers and stir to ensure homogeneity and sample uniformity, if necessary. Remove rocks, sticks, and foreign objects greater than approximately one (1) inch. A one-inch sieve can be used if necessary.
- 7.2.7 Split the sample with the U.S. EPA.
- 7.2.8 Using a hand trowel, collect approximately one (1) quart of the augured soil in the plastic sample bag or jar. For core segments, place each 6-9 inch (nominally 5-7 inch) segment in the plastic sample bag or jar.
- 7.2.9 Label the sample container.
- 7.2.10 Return unused material to the sampling hole and fill in the hole to eliminate possible tripping hazard.
- 7.2.11 Decontaminate the sampling equipment as required by Section 8.
- 7.2.12 When required, mark a pin flag with the sample identification number and place the flag at the center of the sampling location before leaving.

### 7.3 Soil Sample Size

Each soil sample collected for radiological analyses will be a minimum of four (4) pounds and should not exceed 10 pounds. Sample size requirements are detailed in Work Instruction for Sample Preparation Procedure for Gamma Spectral Analysis.

## 8. EQUIPMENT CLEANING

To avoid cross-contamination, the sampling equipment will be cleaned prior to and between samples. The following steps will be followed to clean equipment.

Remove loose contamination by gently tapping/shaking the item.

Using a stainless steel brush or paper towels, remove material that did not dislodge.

If the item appears to be clean (i.e., no visible clinging soil), proceed to the next sampling area.

If the item does not appear to be clean or if a survey with the appropriate instrument does not verify that it is, scrub the item with water. While holding the item over the sampling location, rinse the item with water.

Dry the item with paper towels or repeat the scrubbing sequence as necessary.

Dispose of cleaning materials, plastic sheeting, and associated items as contaminated materials in accordance with instructions provided by the Field Team Leader.

## **9. QUALITY CONTROL**

### **9.1 QC Samples**

To evaluate the variance in the soil sampling protocol, field duplicates will be collected at least once per sampling event and at a minimum of one duplicate per 20 samples specified intervals. These QC samples will be identified and noted in the Field Logbook.

The duplicate will be taken from the homogenized sample collected from one of the four sampling areas. The duplicate will be randomly selected and identified before the sampling begins.

### **9.2 Data Review**

Entries in the Field Logbook will conform to the Field Logbook Standard Operating Procedures, (SOP-215).

The Field Investigation Leader and QA Assistant will resolve any discrepancies that were noted by field personnel in the Field Logbook. See SOP-215 regarding Field Logbook procedures and protocols.

**NOTE:** Discrepancies relating to reported data will be brought to the attention of the Field Investigation Leader or Offsites Project Manager.

## **10. HEALTH AND SAFETY**

Personal protective equipment and clothing, as required by the Health and Safety Section of the Investigation Work Plan, will be used when collecting and handling contaminated soils.

The site radiological conditions will be determined and documented before sampling begins.

## **11. RECORDS**

The following documents will be maintained as quality records:

- Field Logbooks
- Sampling Tracking Forms
- Results of all Calculations and Statistical Analyses Performed

## SAMPLE TRACKING FORM

Date:

Page      of

Sample Number	Matrix (S/W)	Location	Collected For	Comments	Collected By
All samples have been surveyed for removable contamination. None was detected.				Technician	Date/Time
Released by/Company			All samples are listed above are hereby released except for:		Date/Time
Received by/Company			All samples are listed above are hereby received except for:		Date/Time
Received by/Company			Data for all samples listed above are hereby received except for:		Date/Time

# **DuSable Park**

## **Sample Preparation Work Instruction**

**Date:** February 6, 2002

---

### **1. PURPOSE**

This work instruction provides direction for sample preparation work to be performed as part of the limited site investigation at DuSable Park in Chicago, Illinois. Kerr-McGee's split samples will be submitted to Kerr-McGee's laboratory for counting in a one-liter Marinelli geometry. The samples will be moisture corrected and analyzed for the U-238, Th-232 & U-235 decay series using the Canberra HPGe Gamma Detector.

### **2. SCOPE**

Kerr-McGee's laboratory will accept the soil samples collected in the field and prepare them following for gamma spectral analysis according to these instructions.

### **3. REFERENCES**

- 3.1 State of Illinois Department of Nuclear Safety Radioactive Material License Number STA-583
- 3.2 Soil Sampling Work Instruction for DuSable Park
- 3.3 REF Facility Procedure - SOP-WCP 363 "Operation and Calibration of the Canberra HPGe Gamma Detector"
- 3.4 REF Facility Procedure - SOP-WCP 365 "Moisture Analysis"
- 3.5 REF Facility Procedure - SOP-WCP 380 "Use of Laboratory Standard Reference Methods Procedure"

### **4. EQUIPMENT AND MATERIALS**

#### **4.1 Tools, Material, Equipment**

4.1.1 The following equipment is needed to perform this procedure:

- a. 20 ml sample vials
- b. A set of sieves ranging from one-inch to 100 mesh.
- c. Bico-Braum Pulverizer
- d. Riffle splitter
- e. 2 qt plastic jars
- f. aluminum pans
- g. 4-inch Braum-Chipmunk Crusher
- h. analytical balance
- i. Marinelli beakers
- j. zip-lock bags
- k. labels
- l. drying oven

#### 4.2 Precautions, Limits

4.2.1 Personnel are to use extreme caution when using the "Chipmunk Crusher" and the "Pulverizer" because they can cause a serious injury.

4.2.2 All samples not known to be homogeneous must be homogenized prior to analysis.

#### 4.3 Acceptance Criteria

Proper preparation ensures that the samples submitted to the laboratory are representative of the material sampled and suitable for the requested analysis.

### 5. SAMPLE PREPARATION METHODS

#### 5.1 Marinelli Samples

The samples will be counted in a one-liter Marinelli geometry. The samples. The samples will be placed in a plastic collection bag and shall

weigh between four and ten pounds in accordance with the Soil Sampling Work Instruction for DuSable Park.

## 5.2 Sample Receiving

5.2.1 All samples are brought to the sample receiving area and the following information is documented in the "Sample Log".

- a. Sample ID or address
- b. Technician receiving samples
- c. Date/time received

5.2.2 If the samples are not uniquely identified, assign a unique number to each sample and identify the number(s) on each sample and in the Sample Log.

5.2.3 Prepare the sample in accordance with the requirements of the analysis requested.

5.2.4 Sample(s) received for IDNS and/or USEPA are logged as received in the Sample Log Book. The appropriate agency is notified to pick up the sample(s) from the site laboratory. When samples are picked up, note the date and time in the Sample Log Book.

## 5.3 Sample Homogenization

Samples received by the lab will be placed into a clean container for blending. Soil clumps that would not fit into the Marinelli geometry will be broken. The soil will be blended using a steel trowel until an even consistency and color (as visually estimated by the lab personnel) is obtained.

## 5.4 Sample Container Preparation

5.4.1 The tare weight of the empty sample container shall be recorded.

5.4.2 The one-liter Marinelli sample container shall be filled in a manner that minimizes air voids in the soil matrix.

5.4.3 The sample shall be weighed using an analytical balance.

5.4.4 The sample weight shall be moisture corrected in accordance with SOP-WCP 365 "Moisture Analysis". The moisture corrected weight and sample ID number are then written on the lid of the Marinelli

sample container.

- 5.4.5 The lid is securely attached to the container and the sample is ready for gamma spectral analysis in accordance with SOP-WCP 363 "Operation and Calibration of the Canberra HPGe Gamma Detector".

## **6. RECORDS/REPORTS/NOTIFICATIONS**

The following documents will be maintained as quality records:

- 1 Samples shall be retained until all evaluations have been completed and the sample is no longer needed.
- 1 Log Books shall be maintained by the Lab Supervisor until complete and then forwarded to Document Control for storage in the project files.



# **DuSable Park**

## **Downhole Gamma Logging Work Instruction**

**Date:** February 6, 2002

---

### **1. PURPOSE**

This work instruction provides direction for downhole gamma logging work to be performed as part of the limited site investigation at DuSable Park in Chicago, Illinois.

### **2. SCOPE**

Downhole gamma logging will be used primarily to quantify presence of, if any, low-level 11(e)(2) byproduct material present in concentrations exceeding the criteria of 7.1 pCi/g as defined in the U.S. EPA Unilateral Administrative Order (UAO) for the Lindsay Light II Site. The gamma probe is lowered into the test hole and measurements are recorded in six-inch increments.

### **3. REFERENCES**

- 3.1 Surface Gamma Survey Work Instruction,
- 3.2 REF Facility Procedure - SOP-WCP 345 "Surveys of Surface Contamination and Release of Equipment For Unrestricted Use"
- 3.3 REF Facility Procedure - SOP-WCP 347 "Decontamination"
- 3.4 REF Facility Procedure - SOP-WCP 376 "Portable Survey Instrument Operability Checks"
- 3.5 REF Facility Procedure - SOP-WCP 379 "Calibration of the Ludlum Scaler Ratemeter Model 2221."

### **4. REQUIREMENTS**

- 4.1 The Health Physics (HP) Supervisor shall ensure that all HP or other approved technicians who will be performing the health physics duties in accordance with this procedure have been trained and understand their role and responsibilities.

- 4.2 HP or other technicians approved by the HP Supervisor shall ensure that all portable survey equipment used in accordance with this plan is properly functioning and has valid calibration and daily source check stickers. Portable survey equipment shall be source checked daily in accordance with REF Facility Procedure – SOP-WCP 376. The observed counts per minute value corresponding to 7.1 pCi/g for the Ludlum 2221 Ratemeter must be recorded in the appropriate blank on the Borehole Field Log sheet.

## **5. DELINEATION DRILLING METHODS**

### **5.1 Responsibility**

The Offsites Manager or designee is responsible for implementing this activity. The Offsites Manager will appoint a Field Investigation Leader to supervise field activities, maintain records and otherwise conduct QC duties as described in this procedure.

### **5.2 Equipment, Materials and Tools**

5.2.1 Manual equipment to advance test holes.

5.2.2 Trimble Pro-XR GPS unit to record the northing and easting of each test hole.

5.2.3 Ludlum 2221 Digital Ratemeter with a model 44-62 0.5" x 0.5" thallium-activated sodium iodide [NaI(Tl)] scintillator to perform test hole gamma logging.

### **5.3 Drilling and Gamma Logging Procedures**

5.3.1 Utilities will be located prior to performing any ground intrusive activity on a property. The Field Investigation Leader will be responsible for originating a request for a DIGGER Utility Locate for the Site. The phone number for DIGGER is 1-312-744-7000.

5.3.2 Each test hole will be located using the Trimble Pro-XR GPS unit to navigate to the point of the highest surface gamma reading located during the surface gamma survey.

5.3.3 A hollow 2"-diameter O.D. drill pipe will be advanced into the ground by manual means to a depth of 24 inches (2 feet) below grade surface. This depth may be extended, if required, as outlined in Paragraph 5.3.7.

5.3.4 The HP will lower the model 44-62 probe into the geoprobe into the borehole to a depth just below the existing ground surface. This

will be considered the 0" reading. The gamma rate will be recorded following a one-minute counting time. Data will be recorded on the "Borehole Field Log Sheet" provided in this procedure.

- 5.3.5 The HP will then lower the model 44-62 probe into the geoprobe to a depth six-inches below grade surface. At depth, the gamma rate will be recorded following a one-minute counting time. The model 44-62 probe will then lowered to the bottom of the drill pipe in six-inch increments and the gamma rate will be recorded following a one-minute counting time at each six-inch increment. One-minute counts will be accurate because the probe is calibrated using one-minute counts. Data will be recorded on the "Borehole Field Log Sheet" provided in this procedure.
- 5.3.6 If downhole gamma logging results for the boring in the center of each anomaly indicate that 11(e)(2) byproduct material may be present in concentrations exceeding 7.1 pCi/g, additional test holes may be stepped-out in subsequent five-meter increments until results indicate concentrations are less than the criteria for the full vertical extent of the test hole.
- 5.3.7 During test hole gamma logging, if the gamma measurements are increasing with depth, the test hole will be further advanced to achieve two or more successive six-inch increment readings with decreasing readings or until refusal. The field logs will include an explanation of the refusal or other pertinent comments if the bottom two readings are not decreasing with depth.
- 5.3.8 The HP Supervisor or his designee is responsible for reviewing the gamma logs for completeness and data inconsistencies in a timely manner. The Field Investigation Leader is responsible for collecting the reviewed gamma logs from the HP Supervisor.
- 5.3.9 Physical obstructions (i.e. tree, rock, or topography) may prevent test holes from being located at the necessary measured location or from being extended to the minimum required depth of 24-inches. If this occurs, an alternate location should be used that is as close to the preferred location as reasonable and practical.

#### 5.4 Physical Survey and Mapping

The physical location of every test hole will be recorded using the GPS unit. The location of completed test holes will be shown on field maps produced using GPS associated mapping software. Maps will be prepared under the supervision of the Field Investigation Leader.

The Field Investigation Leader is responsible for comparing the map of

completed field test holes to the surface gamma survey and gamma log data to ensure that the test holes cover the study area in accordance with this plan.

## **6. RECORDS/REPORTS/NOTIFICATIONS**

The following documents will be maintained as quality records:

- ξ Field Logbooks
- ξ Test hole gamma logging sheets
- ξ Map of test hole locations
- ξ Data downloads from the GPS unit data logger.

# BOREHOLE FIELD LOG

Page \_\_\_\_ of \_\_\_\_

Date: \_\_\_\_\_ Time: \_\_\_\_\_ Field Technician Name: \_\_\_\_\_  
 Property: \_\_\_\_\_ Property Parcel ID No.: \_\_\_\_\_  
 Instrument Model/Serial Number: 2221/ Probe Model/Serial No.: 44-62/  
 Response Check: Before \_\_\_\_\_ (cpm)

Hole #: \_\_\_\_\_  
 East: \_\_\_\_\_  
 North: \_\_\_\_\_  
 Elev.: \_\_\_\_\_

cpm = 7.2 pCi/g

Type: 2" Geoprobe Pipe

Depth	Counts (cpm)
0"	
6"	
12"	
18"	
24"	
30"	
36"	
42"	
48"	
54"	
60"	

Hole #: \_\_\_\_\_  
 East: \_\_\_\_\_  
 North: \_\_\_\_\_  
 Elev.: \_\_\_\_\_

cpm = 7.2 pCi/g

Type: 2" Geoprobe Pipe

Depth	Counts (cpm)
0"	
6"	
12"	
18"	
24"	
30"	
36"	
42"	
48"	
54"	
60"	

Hole #: \_\_\_\_\_  
 East: \_\_\_\_\_  
 North: \_\_\_\_\_  
 Elev.: \_\_\_\_\_

cpm = 7.2 pCi/g

Type: 2" Geoprobe Pipe

Depth	Counts (cpm)
0"	
6"	
12"	
18"	
24"	
30"	
36"	
42"	
48"	
54"	
60"	

Hole #: \_\_\_\_\_  
 East: \_\_\_\_\_  
 North: \_\_\_\_\_  
 Elev.: \_\_\_\_\_

cpm = 7.2 pCi/g

Type: 2" Geoprobe Pipe

Depth	Counts (cpm)
0"	
6"	
12"	
18"	
24"	
30"	
36"	
42"	
48"	
54"	
60"	

Hole #: \_\_\_\_\_  
 East: \_\_\_\_\_  
 North: \_\_\_\_\_  
 Elev.: \_\_\_\_\_

cpm = 7.2 pCi/g

Type: 2" Geoprobe Pipe

Depth	Counts (cpm)
0"	
6"	
12"	
18"	
24"	
30"	
36"	
42"	
48"	
54"	
60"	

Hole #: \_\_\_\_\_  
 East: \_\_\_\_\_  
 North: \_\_\_\_\_  
 Elev.: \_\_\_\_\_

cpm = 7.2 pCi/g

Type: 2" Geoprobe Pipe

Depth	Counts (cpm)
0"	
6"	
12"	
18"	
24"	
30"	
36"	
42"	
48"	
54"	
60"	

Hole #: \_\_\_\_\_  
 East: \_\_\_\_\_  
 North: \_\_\_\_\_  
 Elev.: \_\_\_\_\_

cpm = 7.2 pCi/g

Type: 2" Geoprobe Pipe

Depth	Counts (cpm)
0"	
6"	
12"	
18"	
24"	
30"	
36"	
42"	
48"	
54"	
60"	

Hole #: \_\_\_\_\_  
 East: \_\_\_\_\_  
 North: \_\_\_\_\_  
 Elev.: \_\_\_\_\_

cpm = 7.2 pCi/g

Type: 2" Geoprobe Pipe

Depth	Counts (cpm)
0"	
6"	
12"	
18"	
24"	
30"	
36"	
42"	
48"	
54"	
60"	

# **DuSable Park**

## **Surveys for Unrestricted Release of Equipment**

### **Work Instruction**

**Date:** March 21, 2002

---

#### **1.0 PURPOSE**

This work instruction establishes the criteria for releasing equipment or materials out of the Exclusion Zone. These methods are to be used to minimize the spread of radioactive contamination.

#### **2.0 SCOPE**

Kerr-McGee's Health Physics personnel shall perform a release survey on equipment or material that has come into contact with material exceeding 7.2 pCi/g (as determined by Surface Gamma Survey or Downhole Gamma Logging) before it leaves the immediate area, and prior to beginning investigation in another area on the Site.

#### **3.0 REFERENCES**

- 3.1 U.S. Atomic Energy Commission Regulatory Guide 1.86 (AECREG 1.86), Dated June 1974.
- 3.2 Surface Gamma Survey Work Instruction for DuSable Park
- 3.3 Downhole Gamma Logging Work Instruction for DuSable Park
- 3.4 Decontamination Work Instruction for DuSable Park

#### **4.0 DEFINITIONS**

##### **4.1 Beta-Gamma to Alpha Decay Ratio**

A thorium-232 decay series produces about 0.5 beta-gamma decays for every one alpha decay. This ratio allows the limits for alpha contamination to be verified using beta-gamma survey instruments.

#### 4.2 Clean Area

This term defines radiation conditions within a specified area. An area where the radiation levels and contamination levels are maintained below 2 mrem/hr and 20 dpm/100 cm<sup>2</sup> removable alpha respectively.

#### 4.3 Contamination Surveys

An assessment that may include, as appropriate, surveys for loose and fixed contamination through the use of direct frisks and large area wipes to locate and quantify the radioactive material present.

#### 4.4 Exclusion Zone

If surface gamma survey results indicate that contamination exceeding 7.2 pCi/g is present at the surface, then a restricted access area will be created at the perimeter of known contamination, with an appropriate buffer.

#### 4.5 Large Area Wipes

Paper towels or masslin used to wipe large areas to identify the presence of loose contamination.

#### 4.6 Unrestricted Release

Release of equipment or materials from the Exclusion Zone to any destination other than a licensed facility.

### 5.0 REQUIREMENTS

#### 5.1 Prerequisites

5.1.1 Health Physics personnel shall ensure that all portable survey equipment used for this procedure are properly functioning and have a valid calibration sticker.

5.1.2 The Health Physics Supervisor or designee shall ensure that all personnel who are required to perform this procedure are properly trained and understand this procedure.

5.1.3 Equipment, vehicles and areas should be free of visible dirt, mud or dust prior to performing a contamination survey.

## 5.2 Tools, Material, Equipment

5.2.1 The following counting equipment, or their equivalents, should be used for performing contamination surveys on equipment and materials:

- (Beta-Gamma) Eberline PRM6 rate meter coupled to an HP-210 shielded GM detector.
- (Beta-Gamma) Ludlum Model 3 rate meter coupled to a Model 44-40 shielded GM detector.
- (Alpha) Ludlum Model 12 rate meter coupled to a 43-20 gas proportional detector.

## 5.3 Precautions, Limits

Direct and removable surveys should not be performed on wet surfaces, for alpha contamination. Wet surfaces should be surveyed only for beta-gamma contamination.

## 5.4 Acceptance Criteria

Prior to unrestricted release from the Exclusion Zone, all vehicles, equipment and materials shall be surveyed for contamination. If contamination exceeding AECREG 1.86 Table 1 limits is found, then the vehicle, equipment, or material should be decontaminated in accordance with the DuSable Park Work Instruction for Decontamination

## 6.0 PROCEDURE


- 6.1 Materials, equipment and vehicles that have come into contact with material exceeding 7.2 pCi/g shall be surveyed for contamination by using large area wipes and by direct frisk as appropriate.
- 6.2 Large area wipes will be frisked for alpha and/or beta/gamma contamination. Results will be compared against removable contamination limits included in AECREG 1.86 Table 1.

## 7.0 ATTACHMENTS

Attachment 1      AECREG 1.86 (Published June 1974)



# ATTACHMENT B



U.S. ATOMIC ENERGY COMMISSION

June 1974

## REGULATORY GUIDE

DIRECTORATE OF REGULATORY STANDARDS

### REGULATORY GUIDE 1.86

#### TERMINATION OF OPERATING LICENSES FOR NUCLEAR REACTORS

##### A. INTRODUCTION

Section 50.51, "Duration of license, renewal," of 10 CFR Part 50, "Licensing of Production and Utilization Facilities," requires that each license to operate a production and utilization facility be issued for a specified duration. Upon expiration of the specified period, the license may be either renewed or terminated by the Commission. Section 50.82, "Applications for termination of licenses," specifies the requirements that must be satisfied to terminate an operating license, including the requirement that the dismantlement of the facility and disposal of the component parts not be inimical to the common defense and security or to the health and safety of the public. This guide describes methods and procedures considered acceptable by the Regulatory staff for the termination of operating licenses for nuclear reactors. The Advisory Committee on Reactor Safeguards has been consulted concerning this guide and has concurred in the regulatory position.

##### B. DISCUSSION

When a licensee decides to terminate his nuclear reactor operating license, he may, as a first step in the process, request that his operating license be amended to restrict him to possess but not operate the facility. The advantage to the licensee of converting to such a possession-only license is reduced surveillance requirements in that periodic surveillance of equipment important to the safety of reactor operation is no longer required. Once this possession-only license is issued, reactor operation is not permitted. Other activities related to cessation of operations such as unloading fuel from the reactor and placing it in storage (either onsite or offsite) may be continued.

A licensee having a possession-only license must retain, with the Part 50 license, authorization for special nuclear material (10 CFR Part 70, "Special Nuclear Material"), byproduct material (10 CFR Part 30, "Rules of General Applicability to Licensing of Byproduct Material"), and source material (10 CFR Part 40, "Licensing of Source Material"), until the fuel, radioactive components, and sources are removed from the facility. Appropriate administrative controls and facility requirements are imposed by the Part 50 license and the technical specifications to assure that proper surveillance is performed and that the reactor facility is maintained in a safe condition and not operated.

A possession-only license permits various options and procedures for decommissioning, such as mothballing, entombment, or dismantling. The requirements imposed depend on the option selected.

Section 50.82 provides that the licensee may dismantle and dispose of the component parts of a nuclear reactor in accordance with existing regulations. For research reactors and critical facilities, this has usually meant the disassembly of a reactor and its shipment offsite, sometimes to another appropriately licensed organization for further use. The site from which a reactor has been removed must be decontaminated, as necessary, and inspected by the Commission to determine whether unrestricted access can be approved. In the case of nuclear power reactors, dismantling has usually been accomplished by shipping fuel offsite, making the reactor inoperable, and disposing of some of the radioactive components.

Radioactive components may be either shipped offsite for burial at an authorized burial ground or secured

#### USAEC REGULATORY GUIDES

Regulatory Guides are issued to describe and make available to the public methods acceptable to the AEC Regulatory staff of implementing specific parts of the Commission's regulations, to delineate techniques used by the staff in evaluating specific problems or postulated accidents, or to provide guidance to applicants. Regulatory Guides are not substitutes for regulations and compliance with them is not required. Methods and solutions different from those set out in the guides will be acceptable if they provide a basis for the findings required by the issuance or continuance of a permit or license by the Commission.

Published guides will be revised periodically, as appropriate, to accommodate comments and to reflect new information or experience.

Copies of published guides may be obtained by request indicating the documents desired to the U.S. Atomic Energy Commission, Washington, D.C. 20545, Attention: Director of Regulatory Standards. Comments and suggestions for improvements in these guides are encouraged and should be sent to the Secretary of the Commission, U.S. Atomic Energy Commission, Washington, D.C. 20545, Attention: Chief, Public Proceedings Staff.

The guides are issued in the following ten broad divisions:

- |                                   |                        |
|-----------------------------------|------------------------|
| 1. Power Reactors                 | 6. Products            |
| 2. Research and Test Reactors     | 7. Transportation      |
| 3. Fuel and Material Facilities   | 8. Occupational Health |
| 4. Environmental and Siting       | 9. Antitrust Review    |
| 5. Materials and Plant Protection | 10. General            |

on the site. Those radioactive materials remaining on the site must be isolated from the public by physical barriers or other means to prevent public access to hazardous levels of radiation. Surveillance is necessary to assure the long term integrity of the barriers. The amount of surveillance required depends upon (1) the potential hazard to the health and safety of the public from radioactive material remaining on the site and (2) the integrity of the physical barriers. Before areas may be released for unrestricted use, they must have been decontaminated or the radioactivity must have decayed to less than prescribed limits (Table I).

The hazard associated with the retired facility is evaluated by considering the amount and type of remaining contamination, the degree of confinement of the remaining radioactive materials, the physical security provided by the confinement, the susceptibility to release of radiation as a result of natural phenomena, and the duration of required surveillance.

### C. REGULATORY POSITION

#### 1. APPLICATION FOR A LICENSE TO POSSESS BUT NOT OPERATE (POSSESSION-ONLY LICENSE)

A request to amend an operating license to a possession-only license should be made to the Director of Licensing, U.S. Atomic Energy Commission, Washington, D.C. 20545. The request should include the following information:

- a. A description of the current status of the facility.
- b. A description of measures that will be taken to prevent criticality or reactivity changes and to minimize releases of radioactivity from the facility.
- c. Any proposed changes to the technical specifications that reflect the possession-only facility status and the necessary disassembly/retirement activities to be performed.
- d. A safety analysis of both the activities to be accomplished and the proposed changes to the technical specifications.
- e. An inventory of activated materials and their location in the facility.

#### 2. ALTERNATIVES FOR REACTOR RETIREMENT

Four alternatives for retirement of nuclear reactor facilities are considered acceptable by the Regulatory staff. These are:

a. **Mothballing.** Mothballing of a nuclear reactor facility consists of putting the facility in a state of protective storage. In general, the facility may be left intact except that all fuel assemblies and the radioactive

fluids and waste should be removed from the site. Adequate radiation monitoring, environmental surveillance, and appropriate security procedures should be established under a possession-only license to ensure that the health and safety of the public is not endangered.

b. **In-Place Entombment.** In-place entombment consists of sealing all the remaining highly radioactive or contaminated components (e.g., the pressure vessel and reactor internals) within a structure integral with the biological shield after having all fuel assemblies, radioactive fluids and wastes, and certain selected components shipped offsite. The structure should provide integrity over the period of time in which significant quantities (greater than Table I levels) of radioactivity remain with the material in the entombment. An appropriate and continuing surveillance program should be established under a possession-only license.

c. **Removal of Radioactive Components and Dismantling.** All fuel assemblies, radioactive fluids and waste, and other materials having activities above accepted unrestricted activity levels (Table I) should be removed from the site. The facility owner may then have unrestricted use of the site with no requirement for a license. If the facility owner so desires, the remainder of the reactor facility may be dismantled and all vestiges removed and disposed of.

d. **Conversion to a New Nuclear System or a Fossil Fuel System.** This alternative, which applies only to nuclear power plants, utilizes the existing turbine system with a new steam supply system. The original nuclear steam supply system should be separated from the electric generating system and disposed of in accordance with one of the previous three retirement alternatives.

#### 3. SURVEILLANCE AND SECURITY FOR THE RETIREMENT ALTERNATIVES WHOSE FINAL STATUS REQUIRES A POSSESSION-ONLY LICENSE

A facility which has been licensed under a possession-only license may contain a significant amount of radioactivity in the form of activated and contaminated hardware and structural materials. Surveillance and commensurate security should be provided to assure that the public health and safety are not endangered.

a. **Physical security** to prevent inadvertent exposure of personnel should be provided by multiple locked barriers. The presence of these barriers should make it extremely difficult for an unauthorized person to gain access to areas where radiation or contamination levels exceed those specified in Regulatory Position C.4. To prevent inadvertent exposure, radiation areas above 5 mR/hr, such as near the activated primary system of a power plant, should be appropriately marked and should not be accessible except by cutting of welded closures or the disassembly and removal of substantial structures

and/or shielding material. Means such as a remote-readout intrusion alarm system should be provided to indicate to designated personnel when a physical barrier is penetrated. Security personnel that provide access control to the facility may be used instead of the physical barriers and the intrusion alarm systems.

b. The physical barriers to unauthorized entrance into the facility, e.g., fences, buildings, welded doors, and access openings, should be inspected at least quarterly to assure that these barriers have not deteriorated and that locks and locking apparatus are intact.

c. A facility radiation survey should be performed at least quarterly to verify that no radioactive material is escaping or being transported through the containment barriers in the facility. Sampling should be done along the most probable path by which radioactive material such as that stored in the inner containment regions could be transported to the outer regions of the facility and ultimately to the environs.

d. An environmental radiation survey should be performed at least semiannually to verify that no significant amounts of radiation have been released to the environment from the facility. Samples such as soil, vegetation, and water should be taken at locations for which statistical data has been established during reactor operations.

e. A site representative should be designated to be responsible for controlling authorized access into and movement within the facility.

f. Administrative procedures should be established for the notification and reporting of abnormal occurrences such as (1) the entrance of an unauthorized person or persons into the facility and (2) a significant change in the radiation or contamination levels in the facility or the offsite environment.

g. The following reports should be made:

(1) An annual report to the Director of Licensing, U.S. Atomic Energy Commission, Washington, D.C. 20545, describing the results of the environmental and facility radiation surveys, the status of the facility, and an evaluation of the performance of security and surveillance measures.

(2) An abnormal occurrence report to the Regulatory Operations Regional Office by telephone within 24 hours of discovery of an abnormal occurrence. The abnormal occurrence will also be reported in the annual report described in the preceding item.

h. Records or logs relative to the following items should be kept and retained until the license is terminated, after which they may be stored with other plant records:

- (1) Environmental surveys,
- (2) Facility radiation surveys,
- (3) Inspections of the physical barriers, and
- (4) Abnormal occurrences.

#### 4. DECONTAMINATION FOR RELEASE FOR UNRESTRICTED USE

If it is desired to terminate a license and to eliminate any further surveillance requirements, the facility should be sufficiently decontaminated to prevent risk to the public health and safety. After the decontamination is satisfactorily accomplished and the site inspected by the Commission, the Commission may authorize the license to be terminated and the facility abandoned or released for unrestricted use. The licensee should perform the decontamination using the following guidelines:

a. The licensee should make a reasonable effort to eliminate residual contamination.

b. No covering should be applied to radioactive surfaces of equipment or structures by paint, plating, or other covering material until it is known that contamination levels (determined by a survey and documented) are below the limits specified in Table I. In addition, a reasonable effort should be made (and documented) to further minimize contamination prior to any such covering.

c. The radioactivity of the interior surfaces of pipes, drain lines, or ductwork should be determined by making measurements at all traps and other appropriate access points, provided contamination at these locations is likely to be representative of contamination on the interior of the pipes, drain lines, or ductwork. Surfaces of premises, equipment, or scrap which are likely to be contaminated but are of such size, construction, or location as to make the surface inaccessible for purposes of measurement should be assumed to be contaminated in excess of the permissible radiation limits.

d. Upon request, the Commission may authorize a licensee to relinquish possession or control of premises, equipment, or scrap having surfaces contaminated in excess of the limits specified. This may include, but is not limited to, special circumstances such as the transfer of premises to another licensed organization that will continue to work with radioactive materials. Requests for such authorization should provide:

(1) Detailed, specific information describing the premises, equipment, scrap, and radioactive contaminants and the nature, extent, and degree of residual surface contamination.

(2) A detailed health and safety analysis indicating that the residual amounts of materials on surface areas, together with other considerations such as the prospective use of the premises, equipment, or scrap, are unlikely to result in an unreasonable risk to the health and safety of the public.

e. Prior to release of the premises for unrestricted use, the licensee should make a comprehensive radiation survey establishing that contamination is within the limits specified in Table I. A survey report should be filed with the Director of Licensing, U.S. Atomic Energy Commission, Washington, D.C. 20545, with a copy to the Director of the Regulatory Operations Regional Office having jurisdiction. The report should be filed at least 30 days prior to the planned date of abandonment. The survey report should:

- (1) Identify the premises;
- (2) Show that reasonable effort has been made to reduce residual contamination to as low as practicable levels;
- (3) Describe the scope of the survey and the general procedures followed; and
- (4) State the finding of the survey in units specified in Table I.

After review of the report, the Commission may inspect the facilities to confirm the survey prior to granting approval for abandonment.

## 5. REACTOR RETIREMENT PROCEDURES

As indicated in Regulatory Position C.2, several alternatives are acceptable for reactor facility retirement. If minor disassembly or "mothballing" is planned, this could be done by the existing operating and maintenance procedures under the license in effect. Any planned actions involving an unreviewed safety question

or a change in the technical specifications should be reviewed and approved in accordance with the requirements of 10 CFR §50.59.

If major structural changes to radioactive components of the facility are planned, such as removal of the pressure vessel or major components of the primary system, a dismantlement plan including the information required by §50.82 should be submitted to the Commission. A dismantlement plan should be submitted for all the alternatives of Regulatory Position C.2 except mothballing. However, minor disassembly activities may still be performed in the absence of such a plan, provided they are permitted by existing operating and maintenance procedures. A dismantlement plan should include the following:

- a. A description of the ultimate status of the facility
- b. A description of the dismantling activities and the precautions to be taken.
- c. A safety analysis of the dismantling activities including any effluents which may be released.
- d. A safety analysis of the facility in its ultimate status.

Upon satisfactory review and approval of the dismantling plan, a dismantling order is issued by the Commission in accordance with §50.82. When dismantling is completed and the Commission has been notified by letter, the appropriate Regulatory Operations Regional Office inspects the facility and verifies completion in accordance with the dismantlement plan. If residual radiation levels do not exceed the values in Table I, the Commission may terminate the license. If these levels are exceeded, the licensee retains the possession-only license under which the dismantling activities have been conducted or, as an alternative, may make application to the State (if an Agreement State) for a byproduct materials license.

TABLE 1

## ACCEPTABLE SURFACE CONTAMINATION LEVELS

NUCLIDE <sup>a</sup>	AVERAGE <sup>b c</sup>	MAXIMUM <sup>b d</sup>	REMOVABLE <sup>b e</sup>
U-nat, U-235, U-238, and associated decay products	5,000 dpm $\alpha$ /100 cm <sup>2</sup>	15,000 dpm $\alpha$ /100 cm <sup>2</sup>	1,000 dpm $\alpha$ /100 cm <sup>2</sup>
Transuranics, Ra-226, Ra-228, Th-230, Th-228, Pa-231, Ac-227, I-125, I-129	100 dpm/100 cm <sup>2</sup>	300 dpm/100 cm <sup>2</sup>	20 dpm/100 cm <sup>2</sup>
Th-nat, Th-232, Sr-90, Ra-223, Ra-224, U-232, I-126, I-131, I-133	1000 dpm/100 cm <sup>2</sup>	3000 dpm/100 cm <sup>2</sup>	200 dpm/100 cm <sup>2</sup>
Beta-gamma emitters (nuclides with decay modes other than alpha emission or spontaneous fission) except Sr-90 and others noted above.	5000 dpm $\beta$ - $\gamma$ /100 cm <sup>2</sup>	15,000 dpm $\beta$ - $\gamma$ /100 cm <sup>2</sup>	1000 dpm $\beta$ - $\gamma$ /100 cm <sup>2</sup>

<sup>a</sup>Where surface contamination by both alpha- and beta-gamma-emitting nuclides exists, the limits established for alpha- and beta-gamma-emitting nuclides should apply independently.

<sup>b</sup>As used in this table, dpm (disintegrations per minute) means the rate of emission by radioactive material as determined by correcting the counts per minute observed by an appropriate detector for background, efficiency, and geometric factors associated with the instrumentation.

<sup>c</sup>Measurements of average contaminant should not be averaged over more than 1 square meter. For objects of less surface area, the average should be derived for each such object.

<sup>d</sup>The maximum contamination level applies to an area of not more than 100 cm<sup>2</sup>.

<sup>e</sup>The amount of removable radioactive material per 100 cm<sup>2</sup> of surface area should be determined by wiping that area with dry filter or soft absorbent paper, applying moderate pressure, and assessing the amount of radioactive material on the wipe with an appropriate instrument of known efficiency. When removable contamination on objects of less surface area is determined, the pertinent levels should be reduced proportionally and the entire surface should be wiped.

# **DuSable Park**

## **Decontamination Work Instruction**

**Date:** March 21, 2002

---

### **1.0 PURPOSE**

The purpose of this work instruction is to provide instructions for the decontamination of personnel and equipment.

### **2.0 SCOPE**

Kerr-McGee's Health Physics personnel shall oversee decontamination of personnel, equipment or materials that have come into contact with material exceeding 7.2 pCi/g (as determined by Surface Gamma Survey, Downhole Gamma Logging or Unrestricted Release Surveys).

### **3.0 REFERENCES**

- 3.1 U.S. Atomic Energy Commission Regulatory Guide 1.86 (AECREG 1.86), Dated June 1974.
- 3.2 Surface Gamma Survey Work Instruction for DuSable Park
- 3.3 Downhole Gamma Logging Work Instruction for DuSable Park
- 3.4 Surveys for Unrestricted Release of Equipment Work Instruction for DuSable Park

### **4.0 DEFINITIONS**

#### **4.1 Clean Area**

This term defines radiation conditions within a specified area. An area where the radiation levels and contamination levels are maintained below 2 mrem/hr and 20 dpm/100 cm<sup>2</sup> alpha respectively.

#### 4.2 Contamination Control Area

This term defines radiation conditions within a specified area. An area that may be contaminated to a level greater than a Clean Area.

#### 4.3 Exclusion Zone

If surface gamma survey results indicate that contamination exceeding 7.2 pCi/g is present at the surface, then a restricted access area will be created at the perimeter of known contamination, with an appropriate buffer.

#### 4.4 Frisking

A personal survey of an individual's clothing and exposed body performed to determine if contamination is present.

#### 4.5 Protective Clothing

Reusable or disposable coveralls, boots and gloves that provide a barrier between contamination and personnel.

#### 4.6 Thermoluminescent Dosimeter (TLD)

A device that measures radiation dose.

### 5.0 REQUIREMENTS

#### 5.1 Prerequisites

5.1.1 Health Physics personnel shall ensure that all portable survey equipment used for this procedure are properly functioning and have a valid calibration sticker.

5.1.2 The Health Physics Supervisor or designee shall ensure that all personnel who are required to perform this procedure are properly trained and understand this procedure.

#### 5.2 Tools, Material, Equipment

5.2.1 Decontamination facility.

5.2.2 Plastic Sheeting, brushes, scrapers, soap, water, scrub brushes and other material as necessary to decontaminate personnel and equipment.

### 5.3 Precautions, Limits

Decontamination of personnel with material other than soap and water will only be done when authorized by the Site Manager, Health Physics Supervisor, or a medical doctor.

### 5.4 Acceptance Criteria

5.4.1 Personnel shall be free of contamination after decontamination.

5.4.2 Material and equipment being decontaminated, for unrestricted release, shall meet the release limits established in Reference 3.4.

## 6.0 PROCEDURE

### 6.1 Personnel Decontamination

6.1.1 Personnel who are contaminated to greater than 100 corrected counts per minute (ccpm) shall notify the health physics technician.

6.1.2 The HPT shall resurvey the individual to determine the exact location of the contamination and document it on the Contaminated Personnel or Personal Effects Report (Attachment 1).

6.1.3 If the contamination is spotty, the HPT shall attempt to decontaminate the individual using swabs or soap and water. If the decontamination is successful, document the results on Attachment 1.

6.1.3.1 If contamination is determined to be in an individual's eyes, the eyes may be flushed, using an eye wash station.

6.1.3.2 If contamination remains in the eyes after flushing or is determined to be in an individual's nose or ears, decontamination will be performed under the direction of qualified medical personnel.

6.1.3.3 Cleansing methods for skin decontamination, in order of harshness are as follows:

- Lifting off with sticky tape.
- Flushing with water.
- Soap and cool water.
- Mild abrasive soap, soft brush, and water.



- Detergent (soap powder).
- Mixture 50% powdered detergent and 50% cornmeal.

6.1.4 If the contamination cannot be easily removed or the contamination is wide spread, the HPT shall escort the individual to Kerr-McGee's West Chicago decontamination facility and notify the Health Physics Supervisor.

6.1.5 The contamination shall be removed by having the individual wash with soap and warm water several times if necessary. The methods listed above may be used by the HPT.

6.1.6 If the decontamination is successful, document the results on Attachment 1.

6.1.7 If, after several attempts, the contamination is not successfully removed, notify the Health Physics Supervisor.

## 6.2 Tool Decontamination

6.2.1 All tools being removed from the Exclusion Zone shall be checked by the HPT.

6.2.2 Tools that are contaminated shall be decontaminated before they can be released from the Exclusion Zone.

6.2.3 Tools shall be decontaminated by the users under the direction of the HPT.

6.2.4 Tools can be decontaminated using scrub brushes and soap and water, wiping with damp rags or wipes, soaking in a decontamination solution, or other safe method approved by the HPT.

6.2.5 All interior surfaces of the tools must be decontaminated as well prior to the tool being unconditionally released.

6.2.6 If the tool cannot be decontaminated after several tries, then the tool shall be placed in a plastic bag and transported to Kerr-McGee's West Chicago decontamination facility and the Health Physics Supervisor shall be notified.

### **6.3 Equipment Decontamination**

- 6.3.1 If equipment used in the limited investigation becomes contaminated with material exceeding 7.2 pCi/g, the contamination shall be removed prior to performing the survey for unrestricted release.
- 6.3.2 The equipment shall be placed on a sheet of plastic, so that any removed contamination will be collected.
- 6.3.3 Contamination shall be removed by light brushing or scraping. If dry methods are not successful, then wet washing with a scrub brush and soapy water would be performed. Spray washing shall only be used as a last alternative.
- 6.3.4 Once the equipment is washed, it will be surveyed by the HPT. The HPT will identify any areas on the equipment that need further decontamination and will make recommendations on how to further decontaminate.
- 6.3.5 All surfaces of the equipment must be decontaminated and surveyed. This includes air intakes, air filters and any internal surface that is likely to be contaminated.
- 6.3.6 Once the equipment has been surveyed by the HPT and determined to comply with the release limits included in the Unrestricted Release of Equipment Work Instruction, then the item can be released.

### **7.0 RECORDS/REPORTS/NOTIFICATIONS**

- 7.1 Release surveys and personnel decontaminations shall be documented on the appropriate form. These records will be forwarded to the project files for retention by the Health Physics Supervisor.
- 7.2 Personal contaminations shall be reported to the Health Physics Supervisor and the Site Manager.

### **8.0 ATTACHMENTS**

- 8.1 Attachment 1 Contaminated Personnel or Personal Effects Report

**Attachment 1 (Example)**  
**CONTAMINATED PERSONNEL OR**  
**PERSONAL EFFECTS REPORT**

DATE OF INCIDENT			TIME OF INCIDENT		
NAME			BADGE NO		
LOCATION OF INCIDENT (SPECIFIC AREA)					
DESCRIPTION	DESCRIBE IN DETAIL ANATOMICAL LOCATION, CONTAMINANT, TYPE OF INJURY, OR CONTAMINATED ARTICLE:				
CONTAMINATED ARTICLE OR AREA	DECONTAMINATION AGENT USED	INSTRUMENT	SURVEY RESULTS BEFORE                      AFTER		FINAL DISPOSITION OF ARTICLES
WOUND COUNT                      /5 MIN		BKGD COUNT                      /5 MIN		SOURCE COUNT                      /5 MIN	
SAFETY MEASURES	PERTINENT SAFETY MEASURES IN EFFECT <div style="display: flex; justify-content: space-around;"><span>YES</span><span>NO</span></div>		IF NO, EXPLAIN		
REMARKS					
EMPLOYEE SIGNATURE			HEALTH PHYSICS SIGNATURE		

# **OPERATION AND CALIBRATION OF THE CANBERRA HPGe GAMMA DETECTOR**

## **1.0 SCOPE**

### **1.1 Purpose**

The Canberra HPGe detector system is used for the non-destructive x-ray and gamma ray spectral analysis of environmental and site operations media. This procedure describes the general operational steps for routine analysis and calibration. Calibrations are performed in reproducible, standardized geometries to ensure accuracy and precision of analytical results.

### **1.2 Applicability**

This procedure applies to the quantitative and qualitative x-ray and gamma ray analysis of environmental and site operations media. Quantitative analyses are performed only on standardized geometries. Qualitative analyses are performed for identification purposes only, including any non-standard media.

## **2.0 REFERENCES**

- 2.1 32 Illinois Administrative Code, Parts 310 and 340, Standards for Protection Against Radiation
- 2.2 32 Illinois Administrative Code, Part 400, Notices, Instructions and Reports to Workers; Inspections
- 2.3 West Chicago Project, Health and Safety Plan for Decommissioning Activities at the Kerr-McGee Chemical Corporation Rare Earths Facility, West Chicago, Illinois
- 2.4 State of Illinois Department of Nuclear Safety Radioactive Material License Number STA-583
- 2.5 Canberra PROCOUNT Operations Manual
- 2.6 Canberra Germanium Detectors User's Manual
- 2.7 Canberra Operating Manuals (the equations for calculating sample activity)
- 2.8 Amersham Certificate of Calibration (DV648)

### **3.0 DEFINITIONS**

None.

### **4.0 REQUIREMENTS**

#### **4.1 Prerequisites**

- 4.1.1 The system records live time, clock time and dead time and stores this information with the sample spectra. Live time is used for all sample activity calculations.

#### **4.2 Tools, Material, Equipment**

- 4.2.1 Digital Equipment Company (DEC) MicroVax 3000 workstation or equivalent.
- 4.2.2 Canberra high-purity germanium (HPGe) detector or equivalent. The HPGe detector(s) is a reverse electrode type, with very thin ion implanted electrode. The cryostat is topped with a very thin aluminum endcap. This combination maximizes sensitivity for low energy photopeaks by offering improved resolution along with flatter efficiency response. The detector(s) is approximately 50 mm diameter by 50mm thick and around 25% efficient (relative to a 3" X 3" NaI(Tl)).
- 4.2.3 Canberra spectroscopy amplifier Model 9645 or equivalent.
- 4.2.4 Canberra high voltage power supply Model 9645 or equivalent.
- 4.2.5 Canberra analog-to-digital converter (ADC) Model 9633 or equivalent.
- 4.2.6 Canberra acquisition interface module (AIM) Model 556 or equivalent.
- 4.2.7 Canberra nuclear instrumentation BIN Model 2100 or equivalent.
- 4.2.8 Nuclear Data remote parallel interface (RPI) or equivalent.

#### **4.3 Precautions, Limits**

- 4.3.1 Background checks will be performed on a daily or prior to use basis.
- 4.3.2 Instrument response or efficiency checks will be performed on a daily or prior to use basis.

- 4.3.3 NIST traceable standards should only be used for calibrations.
- 4.3.4 Amersham Mixed Gamma Standards do not require coincidence/summing corrections. NIST SRM 4276C Mixed-Radionuclide Solution Standard requires corrections for coincidence/summing.

#### 4.4 Acceptance Criteria

- 4.4.1 Samples shall be analyzed for a sufficient time to achieve the required sensitivities. Typically counting times of 15 to 1000 minutes are used.

The Project required sensitivities vary for soil, water and air particulate samples. Attachment 1 provides the sensitivity for 1500 grams of soil in a one-liter Marinelli beaker geometry, using a 1000 second counting time. Soil sensitivities of  $\leq 1$  pCi/g for Ra-226 and Ra-228, and  $\leq 5$  pCi/g for U-238, using appropriate progeny, are adequate for both the off-Site (Superfund) and on-Site (Rare Earth Facility) projects.

## 5.0 PROCEDURE

### 5.1 Initial Detector Electronics Setup

- 5.1.1 Menu items can typically be selected by typing the option number and selecting the return function key. Alternately, the menu item can be highlighted by using the up and down arrow keys and selecting the PF1 function key.

- 5.1.2 Verify or establish the high voltage power supply settings.

NOTE: Polarity is critical and should be noted and recorded in the maintenance log. If polarity is changed the detector will be damaged.

5.1.2.1 Click on the MCA option box located in the left margin of the MCA Window using the mouse.

5.1.2.2 Click on the Adjust option box located in the left margin of the MCA Window.

5.1.2.3 Click on the HVPS option box. Confirm that the initial settings are as follows:

Voltage:	3500 V.
Status:	On
Over/Inh. State:	Clear
Over Latch:	Disable
Inh. Latch:	Disable
Inh. Signal:	5 V.

### 5.1.3 Verify or establish the amplifier gain settings.

**5.1.3.1** Click on the MCA option box located in the left margin of the MCA Window.

**5.1.3.2** Click on the Adjust option box located in the left margin of the MCA Window.

**5.1.3.3** Click on the AMPLIFIER option box. Confirm that the initial settings are as follows:

Coarse Gain:	X2.5
Fine Gain:	(adjustable)
S-Fine Gain:	1.0000X
BLR Mode:	Sym
PUR:	On
Preamp Type:	RC
Shaping Mode:	Gaussian
Shaping Time:	4 $\mu$ Sec
Input Mode:	Normal
Input Polarity:	Negative
LTC Mode:	Normal
Inh. Polarity:	Positive

**5.1.3.4** The fine gain adjustment is described in the following section.

**5.1.3.5** Log the amplifier gain settings in the HPGe logbook.

### 5.1.4 Verify or establish the initial ADC Settings

**5.1.4.1** Click on the MCA option box located in the left margin of the MCA Window using the mouse.

**5.1.4.2** Click on the Adjust option box located in the left margin of the MCA Window.

**5.1.4.3** Click on the ADC option box. Confirm that the initial settings are as follows:

Conv. Gain:	8192
Offset:	0
LLD:	2.00%
ULD:	110%
Zero:	$\pm 0.500\%$
Acq. Mode:	PHA
Anticoinc.:	Coinc
Late Coinc.:	Early
Peak Detect:	Auto
Xfer Timing:	Overlap
LTC/PUR:	LG

**5.1.5** Establish or verify the amplifier gain and ADC zero settings.

**5.1.5.1** Place a mixed gamma calibration standard that includes at least two well-spaced photon energies spanning the energy calibration range of interest. A mixed gamma standard containing a low energy nuclide such as Cd-109 (88.03 keV) and a high energy nuclide such as Y-88 (1836.01 keV) should suffice.

**5.1.5.2** Click on the Acquire On option box in the left margin of the MCA window to initiate spectral data acquisition.

**5.1.5.3** Note the peak centroid channel locations for the 88-keV and 1836-keV lines. The recommended peak channel locations for a nominal 0.5 keV/channel system gain are as follows:

Nuclide	Energy(keV)	Peak Channel
Cd-109	88.03	176 $\pm$ 2
Y-88	1836.01	3672 $\pm$ 2
Difference	1747.98	3496 $\pm$ 2

**5.1.5.4** Calculate the peak channel difference for the 88-keV and 1836-keV photon lines and compare to the preceding table.



**5.1.5.4.1** If the observed channel difference is too small, increase the amplifier gain setting by clicking on the Fine Gain option box with the mouse and adjusting.

**5.1.5.4.2** If the observed channel difference is too large, decrease the amplifier gain setting by clicking on the Fine Gain option box with the mouse and adjusting.

**5.1.5.5** Erase and acquire a new gamma spectrum by clicking on the Clear option box and repeat above steps until the desired channel difference is achieved.

**5.1.5.6** Record any changes to the amplifier settings in the HPGe counting log and proceed to ADC Setup.

#### **5.1.6 Analog-to-Digital Converter (ADC) Setup**

**5.1.6.1** Note the peak centroid channel location of the 1836-keV gamma line and compare to preceding table.

**5.1.6.1.1** If the observed peak centroid channel location is less than the desired channel location, increase the ADC zero setting.

**5.1.6.1.2** If the peak centroid channel location is greater than the desired channel location, decrease the ADC zero setting.

**5.1.6.1.3** Erase and acquire a new gamma spectrum and repeat above steps until the desired peak channel location is achieved.

**5.1.6.2** Record any changes to the ADC zero settings in the counting room log.

### **5.2 Calibrations**

#### **5.2.1 Initial Energy/Shape Calibration**

**5.2.1.1** This is the initial energy and peak shape calibration. This type of calibration is only performed when initially setting up the HPGe detector system for the first time. Performing additional calibration geometries is described in the next section.

Efficiency vs. energy curves are established (or re-established) each time the HPGe detector is calibrated see 5.2.2).

- 5.2.1.2 Select option #1 Gamma Counting from the Sample Counting Main Menu.
- 5.2.1.3 Select option #6 Calibrate a Detector from the Gamma Count Main Menu.
- 5.2.1.4 Select option #1 Energy/Shape Initial Calibration from the Detector Calibration Main Menu.
- 5.2.1.5 Select the desired detector at the Nbr Detector Name prompt from the Detector Main Menu.
- 5.2.1.6 Enter the analysis live time in seconds at the Preset Live Time prompt. The default time format is in seconds. Spectrum acquisition times should be sufficient to obtain well resolved photopeaks with at least 10,000 net counts in each of the photopeak areas.
- 5.2.1.7 Enter a "Yes" at the Wait for Acquisition prompt.
- 5.2.1.8 Place a NIST traceable source on the detector in the geometry of interest. A mixed gamma reference source with non-interfering calibration energies spanning the nominal energy range of 80 to 2000 keV should be used.
- 5.2.1.9 Enter a Return function key to continue with the Calibration.
- 5.2.1.10 Enter a Y (Yes) at the "Would you like to use the spectrum presently in the detector prompt".
- 5.2.1.11 Enter a N (No) at the Do you want to turn acquisition off to calibrate prompt.
- 5.2.1.12 Enter the Select function key at the option #1 Energy Calibration and option #2 FWHM Calibration prompt to select both energy and FWHM calibration options. The options will be underlined indicating both are selected.
- 5.2.1.13 Select the appropriate calibration certificate number option at the Certificate Menu prompt.

- 5.2.1.14 Move the mouse and cursor to the low energy photon peak and select option #1 low energy peak to highlight.
- 5.2.1.15 Move the mouse and cursor to the high energy photon peak and select option #2 high energy peak to highlight.
- 5.2.1.16 Enter the PF1 function key to accept low and high energy peak marker information.
- 5.2.1.17 Select the Perform/Update Calibration option at the Calibration Main Menu.
- 5.2.1.18 Select the Review option at the Calibration Review Main Menu. Energy calibration results should be within  $\pm 2$  percent of the known energies. The fitted shape or FWHM calibration results should be within  $\pm 15$  percent of the experimentally observed FWHM shapes.
- 5.2.1.19 Enter the PF3 Exit function key to update calibration information.

## 5.2.2 Energy/Shape/Efficiency Calibration

- 5.2.2.1 Select option #1 Gamma Counting from the Sample Counting Main Menu.
- 5.2.2.2 Select option #6 Calibrate a Detector from the Gamma Count Main Menu.
- 5.2.2.3 Select option #2 Energy/Shape/Efficiency Update Calibration from the Detector Calibration Main Menu.
- 5.2.2.4 Select the desired detector at the Nbr Detector Name prompt from the Detector Main Menu.
- 5.2.2.5 Enter the analysis live time in seconds at the Preset Live Time prompt. The default time format is in seconds. Spectrum acquisition times should be sufficient to obtain well resolved photopeaks with at least 10,000 net counts in each of the photopeak areas.
- 5.2.2.6 Enter a "Yes" at the Wait for Acquisition prompt.

- 5.2.2.7 Place a NIST traceable source on the detector in the geometry of interest. A mixed gamma reference source with non-interfering calibration energies spanning the nominal energy range of 80 to 2000 keV should be used.
- 5.2.2.8 Enter a Return function key to continue with the Calibration.
- 5.2.2.9 Enter a Y (Yes) at the "Would you like to use the spectrum presently in the detector" prompt.
- 5.2.2.10 Enter a N (No) at the Do you want to turn acquisition off to calibrate prompt.
- 5.2.2.11 Enter the PF1 Select function key at the option #1 Energy Calibration option #2 FWHM Calibration and option #3 Efficiency prompt to select all three calibration options. The options will be underlined indicating selection.
- 5.2.2.12 Select the appropriate calibration certificate number option at the Certificate Menu prompt.
- 5.2.2.13 Move the mouse and cursor to the low energy photon peak and select option #1 low energy peak to highlight.
- 5.2.2.14 Move the mouse and cursor to the high energy photon peak and select option #2 high energy peak to highlight.
- 5.2.2.15 Enter the Select function key to accept low and high energy peak marker information.
- 5.2.2.16 Select the Perform/Update Calibration option at the Calibration Main Menu.
- 5.2.2.17 Select option #1 Energy, #2 FWHM, #3 Efficiency at the Calibration Review Main Menu.
- 5.2.2.18 Enter the PF3 Exit function key to update calibration information.
- 5.2.2.19 Enter a Y (Yes) at the Would you like to generate calibration report prompt.
- 5.2.2.20 Review the Calibration Report and ensure that the residuals from the fitted values as compared to the experimentally observed values are within the following acceptance criteria:

FWHM:  $\pm 15 \%$   
Efficiency:  $\pm 10 \%$

**5.2.2.21** Verify the efficiency calibration by analyzing a known standard of the same geometry as a sample as described in the following section.

### 5.3 Routine Operations

#### 5.3.1 Daily Checks

5.3.1.1 The Efficiency checks are performed as follows:

**5.3.1.1.1** Place the check source in the proper counting geometry on the HPGe detector.

Note: A record of the check is maintained in the computer.

**5.3.1.1.2** Select option #1 Gamma Counting from the Sampling Counting Main Menu.

**5.3.1.1.3** Select option #5 Quality Control from the Gamma Counting Main Menu.

**5.3.1.1.4** Select option #1 Calibration Check from the Quality Control Menu.

**5.3.1.1.5** Select the desired detector at the Nbr Detector Name prompt from the Detectors menu.

**5.3.1.1.6** Select the proper geometry option.

**5.3.1.1.7** Select the appropriate quality control certificate option at the Nbr Certificate Name prompt from the Certificate Files Menu.

**5.3.1.1.8** Place the check source for the geometry and QA file selected in step G on the detector and Enter a Return to begin acquisition. Data acquisition will automatically begin for the preset time established in the quality control check file.

**5.3.1.1.9** Review the Calibration Check report and confirm the low and high energy points have passed the bounds test for the following information:

Peak Centroid

Peak FWHM

Peak Efficiency (Decay Corrected Activity)

**5.3.1.1.10** If any of the parameters fail, repair the obvious (such as a faulty energy calibration) and repeat check.

**5.3.1.1.11** *Deleted*

**5.3.1.2** Background Checks are performed as follows:

**5.3.1.2.1** Open the shell door and check to ensure counting cave is empty. Close shell door prior to proceeding.

Note: A record of the check is maintained in the computer.

**5.3.1.2.2** Select option #1 Gamma Counting from the Sampling Counting Main Menu.

**5.3.1.2.3** Select option #5 Quality Control from the Gamma Counting Main Menu.

**5.3.1.2.4** Select option #2 Background Check from the Quality Control Menu.

**5.3.1.2.5** Select the desired detector at the Nbr Detector Name prompt from the Detectors menu.

**5.3.1.2.6** Verify step 5.3.2.a. prior to proceeding and Enter a Return to start acquisition. Data acquisition will automatically begin for the preset time established in the background control check file.

**5.3.1.2.7** Review the Background Check report for the presence of significant peaks indicating contamination. Decontaminate detector or detector chamber as necessary.

**5.3.1.3** *Deleted*

### **5.3.2 Routine Sample Analysis**

- 5.3.2.1** Place the sample in the proper counting geometry on the HPGe detector.
- 5.3.2.2** Record sample identification information in the Germanium Sample Log.
- 5.3.2.3** Select option #1 Count a Sample from the Gamma Counting Main Menu.
- 5.3.2.4** Select option #1 the desired detector at the Nbr Detector Name prompt from the Detectors Menu.
- 5.3.2.5** Select option desired analysis sequence from the Nbr Analysis Name prompt.
- 5.3.2.6** Select the appropriate sample geometry at the Nbr Geometry prompt from the Geometry Files menu.
- 5.3.2.7** Place sample on detector in appropriate geometry configuration. Enter a RETURN to continue. The system will respond with the Acquisition has started message.
- 5.3.2.8** Enter the Preset Live Time in seconds at the prompt, if needed. They are normally pre set already.
- 5.3.2.9** Enter the Sample ID at the prompt.
- 5.3.2.10** Enter the Sample Quantity or mass in grams.
- 5.3.2.11** Enter the desired Sample Units (i.e., grams) at the prompt. Normally, units are pre-set.
- 5.3.2.12** Enter the Sample Date/Filter End Date and Time at the prompt.
- 5.3.2.13** Record Sample Number End from prompt as File # in the Germanium Sample Log.
- 5.3.2.14** Review or edit inputs as necessary and select the PF1 function key to process/accept information.
- 5.3.2.15** The system message Submitting the procedure which waits for acquisition to finish will be displayed on the monitor. The

analysis report will be printed at the completion of counting (see example Attachment #1).

5.2.3.16 At the completion of counting, analysis results will be stored to a results file on the MicroVax computer.

5.2.3.17 Select the PF3 function to return the counter to the Sample Counting Main Menu.

## 6.0 RECORDS/REPORTS/NOTIFICATIONS

6.1 Submit all *results to* the *Health Physics Supervisor*.

## 7.0 ATTACHMENTS

7.1 Attachment #1 HJPGe detector minimum detectable activities (MDA) as calculated per US-NRC regulatory Guideline 4.14. (Example)

7.2 Attachment #2 ~~Deleted~~



**Attachment 1**  
**(Example)**  
**Page 1 of 8**

Kerr-McGee Gamma Report

Generated 15-JUN-1995 08:50:22

Configuration : DKA200:[GAMMA.SCUSR.ARCHIVE]BKG\_MARINELLI\_GE1\_MARINELLI\_6831.CNF;1

---- Sample Information ----

Sample Title :  
 Sample ID : Marinelli Sample Quantity : 1.00000E+00 EA  
 Sample Type : Sample Geometry :  
 Sample Number : 6831 Spctrm Collector : RAY LANCASTER  
 Analyzed By :

---- Sample Deposition Information ----

Dep. Correction? : No Dep. Duration :  
 Deposition Start : Deposition End : 17-FEB-1995 00:00:00

---- Sample Decay/Count Information ----

Sample Date : 17-FEB-1995 00:00:00 Acquisition date : 17-FEB-1995 15:07:19  
 Decay time : 0 15:07:19.21 % dead time : 0.1%  
 Elapsed live time: 0 00:16:40.00 Elapsed real time: 0 00:16:40.95

---- Detector Parameters ----

Energy cal. time : 13-FEB-1995 12:10:32 Energy cal. oper.: RAY LANCASTER  
 Detector name : GE1 Counting geometry: Marinelli  
 Effic. cal. time : 13-FEB-1995 14:34:23 Effic. cal. oper.: RAY LANCASTER

---- Processing Parameters ----

Start channel : 50 End channel : 8192  
 Sensitivity : 5.00000 Gaussian Sens. : 10.00000  
 Critical level? : No Propagate Errors?: Yes  
 Empirical Eff? : Yes Library-based eff: Yes  
 Energy tolerance : 2.00000 Half life ratio : 30.00000  
 Abundance limit : 75.00000 WTM error limit : 3.00000  
 MDA Width (FWHM) : 3.00000 MDA Confid Level : 5.00000 %

Pk	It	Energy	Area	Bkgnd	FWHM	Channel	Left	Pw	Cts/Sec	%Err	Fit
1	0	511.35	29	0	1.52	1022.83	1018	12	2.90E-02	18.6	

**Attachment 1**  
**(Example)**  
**Page 2 of 8**

Interference Report  
Sample ID : Marinelli

Page : 2  
Acquisition date : 17-FEB-1995 15:07:19

No interference correction performed

Attachment 1  
(Example)  
Page 3 of 8

Summary of Nuclide Activity

Page : 3

Sample ID : Marinelli

Acquisition date : 17-FEB-1995 15:07:19

Total number of lines in spectrum	1
Number of unidentified lines	0
Number of lines tentatively identified by NID	1 100.00%

\*\*\*\* There are no nuclides meeting summary criteria \*\*\*\*

Flags: "K" = Keyline not found

"M" = Manually accepted

"E" = Manually edited

"A" = Nuclide specific abn. limit

**Attachment 1  
(Example)  
Page 4 of 8**

Nuclide Line Activity Report  
Sample ID : Marinelli

Page : 4  
Acquisition date : 17-FEB-1995 15:07:19

Flag: "\*" = Keyline

**Attachment 1  
(Example)  
Page 5 of 8**

Unidentified Energy Lines

Page : 5

Sample ID : Marinelli

Acquisition date : 17-FEB-1995 15:07:19

It	Energy	Area	Bkgnd	FWHM	Channel	Left	Pw	Cts/Sec	%Err	%Eff	Flags
0	511.35	29	0	1.52	1022.83	1018	12	2.90E-02	37.1	1.32E+00	T

Flags: "T" = Tentatively associated

**Attachment 1  
(Example)  
Page 6 of 8**

Rejected Report

Page : 6

Sample ID : Marinelli

Acquisition date : 17-FEB-1995 15:07:19

Nuclide	Half-life	Ratio	Energy	%Abund	Activity	%Error	2-Sigma	Rejected by
TL-208	1.41E+10Y	0.00	74.96	3.34	---	Not Found	---	Abun.
			84.90	1.52	---	Not Found	---	
			510.84	21.60	2.738E-04	45.73		
			583.14*	84.20	---	Not Found	---	
			860.37	12.46	---	Not Found	---	
			2614.66	99.80	---	Not Found	---	
% Abundances Found =			9.69		(Abn. Limit = 75.00%)			

Flag: \*\*\* = Keyline

**Attachment 1**  
**(Example)**  
**Page 7 of 8**

Minimum Detectable Activity Report  
Sample ID : Marinelli

Page : 7  
Acquisition date : 17-FEB-1995 15:07:19

Nuclide	Bckgnd Sum	Energy (keV)	MDA (pCi/EA)
K-40	6.	1460.81	3.8628E+02
TL-208	4.	583.14	1.8799E+01
PB-210	9.	46.50	4.2948E+02
BI-212	6.	727.17	3.0388E+02
PB-212	11.	238.63	2.6746E+01
BI-214	5.	609.31	3.7202E+01
PB-214	5.	351.92	3.0523E+01
RA-226	19.	186.21	3.9854E+02
AC-228	2.	911.07	5.6099E+01
TH-230	6.	67.67	1.9249E+03
PA-234M	8.	92.59	1.2858E+02
TH-234	8.	92.59	1.2858E+02
U-235	16.	185.71	2.2349E+01

**Attachment 1  
(Example)  
Page 8 of 8**

Combined Activity-MDA Report  
Sample ID : Marinelli

Page : 8  
Acquisition date : 17-FEB-1995 15:07:19

---- Non-Identified Nuclides ----

Nuclide	Key-Line Activity (pCi/EA)	K.L. Ided	Act error	MDA (pCi/EA)	MDA error	Act/MDA
K-40	1.203E+02		3.339E+02	3.863E+02	6.085E+01	0.311
TL-208	-1.642E+01		2.618E+01	1.880E+01	4.185E+00	-0.873
PB-210	1.809E+02		3.565E+02	4.295E+02	1.598E+02	0.421
BI-212	1.775E+02		2.192E+02	3.039E+02	4.737E+01	0.584
PB-212	6.179E+00		2.457E+01	2.675E+01	5.070E+00	0.231
BI-214	-1.132E+01		4.289E+01	3.720E+01	7.478E+00	-0.304
PB-214	-8.746E+00		3.272E+01	3.052E+01	5.483E+00	-0.287
RA-226	8.464E+01		3.678E+02	3.985E+02	7.249E+01	0.212
AC-228	-1.709E+01		6.757E+01	5.610E+01	9.084E+00	-0.305
TH-230	-8.953E+02		2.240E+03	1.925E+03	3.535E+02	-0.465
PA-234M	-1.519E+03		5.105E+03	1.286E+02	1.951E+01	-11.811
TH-234	-1.153E+01		1.221E+02	1.286E+02	1.951E+01	-0.090
U-235	-4.287E+01		9.668E+01	2.235E+01	4.126E+00	-1.918



# **MOISTURE ANALYSIS**

## **1.0 SCOPE**

### **1.1 Purpose**

This procedure shall be used to determine the moisture content in soils at the West Chicago Project.

### **1.2 Applicability**

This procedure applies to all analyses of moisture in soils at the West Chicago Project.

## **2.0 REFERENCES**

### **2.1 MAX Moisture Analyzer User Manual.**

## **3.0 DEFINITIONS**

### **3.1 None**

## **4.0 REQUIREMENTS**

### **4.1 Prerequisites**

4.1.1 The MAX-50 Moisture Analyzer is operational and warmed up for at least 20 minutes.

4.2.2 The MAX-50 shall be calibrated prior to use.

### **4.2 Tools and Equipment**

4.2.1 Calibration weights, a 10 gram and a 6 gram

4.2.2 Weighing pans, AZI stock number 990-0008-00 or equivalent

4.2.3 MAX-50 Moisture Analyzer

4.2.4 Scale, if not using the MAX-50 Moisture Analyzer

4.2.5 Oven, if not using the MAX-50 Moisture Analyzer

#### 4.3 Precautions, Limits

4.3.1 The MAX-50 Moisture Analyzer uses a heating element in the lid that, while in use, can cause serious burns if in contact with unprotected skin.

4.3.2 The MAX-50 Moisture Analyzer has a max weight capacity of 20 grams.

4.3.3 The balance in the MAX-50 Moisture Analyzer is a precision balance. Care should be used when placing or removing items so that the balance is not damaged.

4.3.4 Gloves shall be worn when handling the calibration weights.

4.3.5 Exercise care when transferring samples in to or out of the oven.

#### 4.4 Acceptance Criteria

4.4.1 The acceptable range for the calibration test on the MAX-50 Moisture Analyzer is between 37.48 - 37.54 %.

### 5.0 PROCEDURE

#### 5.1 Calibration of the MAX-50 Moisture Analyzer

5.1.1 Verify the analyzer is on and warmed up for at least 20 minutes.

5.1.2 Open the lid and place an aluminum pan onto the sample tray support.

5.1.3 Close the lid and press the start button.

5.1.4 When the "LOAD" light illuminates, press the "% SAMPLE" button.

5.1.5 Open the lid and place the 10 gram and the 6 gram weight on the sample pan.

5.1.6 Close the lid and observe the display. If the balance is operating the display should read 75-85%.

5.1.7 If the display does not read between specified range, press the reset button, remove the calibration weights, and place the analyzer out of service.

5.1.8 Close the lid to start the analysis cycle.

**NOTE**

The heat lamp will energize as part of the analysis cycle. Care should be used when opening the lid and handling the weights.

5.1.9 When the heat lamp illuminates, open the lid and remove the 6 gram weight.

**NOTE**

Care must be used when removing the weight. If the sample pan is disturbed, the red "SYSTEM FAILURE" light will illuminate and the display will read "1".

5.1.10 If a system failure occurs, press the reset button, remove the calibration weights, and restart the test at step 5.1.5.

5.1.11 Close the lid and wait for the analysis cycle to complete.

5.1.12 When the green "FINAL" light illuminates, indicating the completion of the analysis, the display will indicate the % moisture. If the display does not read 37.48 to 37.54%, place the analyzer out of service.

5.1.13 If the display is within the acceptable range, initial the Lab Daily Routine Sheet for the calibration.

5.1.14 Open the lid and remove the calibration weights, return them to their storage location, and close the lid of the analyzer.

5.2 Moisture Determination Using the MAX 50 Moisture Analyzer

5.2.1 Verify the analyzer is energized and has warmed up for at least 20 minutes.

5.2.2 Verify analyzer calibration by observing the sign off on the Lab Daily Routine Sheet.

5.2.3 Open the lid and remove any sample pans.

5.2.4 Place a sample pan on the sample pan support.

5.2.5 Close the lid and press the "START" or the "HISTART" button.

**NOTE**

Maximum sample weight of 20g may be analyzed. The display will

read out the percent of sample. When *sufficient* sample has been placed on the sample pan the analyzer will beep and the amber "CLOSE" light will illuminate.

- 5.2.6 When the load light illuminates, open the lid and place the sample in the sample pan.
- 5.2.7 When the "CLOSE" light illuminates, close the lid to start the analysis cycle.
- 5.2.8 When the green "FINAL" light illuminates, the analysis cycle is complete. The display will read the % Moisture.
- 5.2.9 Record the % Moisture on the Moisture Analysis Log, Attachment 1.
- 5.2.10 Open the lid, remove the sample pan, and close the lid.
- 5.2.11 Repeat steps 5.2.4 to 5.2.10 for each sample to be analyzed.

### 5.3 Moisture Determination using a Scale

- 5.3.1 Verify the scale to be used has been calibrated for the day by observing the sign off on the Lab Daily Routine Sheet.
- 5.3.2 Weigh the sample and determine the net weight of the sample.
- 5.3.3 Dry the sample for at least 24 hours at a minimum of 100 degrees C.
- 5.3.4 Reweigh the sample and determine the net weight.
- 5.3.5 Subtract the net weight measured in 5.3.4 from the net weight measured in step 5.3.2.
- 5.3.6 Divide the value obtained in step 5.3.5 by the weight obtained in 5.3.2 and multiply the value by 100.
- 5.3.7 Record the value from 5.3.6 as the % Moisture on the Moisture Analysis Log.

## 6.0 RECORDS/REPORTS/NOTIFICATIONS

### 6.1 Records

6.1.1 Lab Daily Routine Sheet

6.1.2 Moisture Analysis Log

6.2 Retention

Records generated in the performance of this procedure will be retained for the duration of the West Chicago Project.

6.3 Reports

Report analysis results as required for that sample type.

6.3 Notifications

Notify lab supervision of conditions requiring analyzer to be place out of service.

## **7.0 ATTACHMENTS**

7.1 *Attachment 1* Typical Moisture Analysis Log

**MOISTURE ANALYSIS LOG**

<b>DATE</b>	<b>TIME</b>	<b>MAX-50 USED (Y/N)</b>	<b>SCALE SERIAL #</b>	<b>AS RECEIVED NET WEIGHT</b>	<b>DRY NET WEIGHT</b>	<b>% MOISTURE</b>	<b>TECH INITIALS</b>

APPROVED BY \_\_\_\_\_ DATE: \_\_\_\_\_

# **PORTABLE SURVEY INSTRUMENT OPERABILITY CHECKS**

## **1.0 SCOPE**

### **1.1 Purpose**

To provide a means to document the operability of portable survey instruments.

### **1.2 Applicability**

*This procedure is required of all project personnel performing radiological surveys using portable instruments.*

## **2.0 REFERENCES**

- 2.1 32 Illinois Administrative Code, Parts 310 and 340, Standards for Protection Against Radiation
- 2.2 32 Illinois Administrative Code, Part 400, Notices, Instructions and Reports to Workers; Inspections
- 2.3 West Chicago Project, Health and Safety Plan for Decommissioning Activities at the Kerr-McGee Chemical Corporation Rare Earths Facility, West Chicago, Illinois
- 2.4 ANSI N323-1978

## **3.0 DEFINITIONS**

### **Source Check**

A test of an instrument's response to a known radiation field in order to verify operability of the instrument.

## **4.0 REQUIREMENTS**

#### 4.1 Prerequisites

None.

#### 4.2 Tools, Material, Equipment

4.2.1 Calibrated survey meters.

4.2.2 Necessary radioactive sources to verify operability of each type of instrument.

#### 4.3 Precautions, Limits

Do not subject portable survey meters to physical abuse or water.

#### 4.4 Acceptance Criteria

4.4.1 The survey instruments indicate a satisfactory response to the battery check prior to *each day of use*.

4.4.2 The survey instruments indicate a satisfactory response to the check source (mean  $\pm$  20%) prior to *each day of use*.

### 5.0 PROCEDURE

5.1 Portable survey instruments will be source *checked, after* repair and calibration, or prior to *each day of use*.

#### 5.2 Alpha Instruments:

5.2.1 Select the desired instruments.

5.2.2 Record the current date and time on Attachment 1.

5.2.3 Check the calibration due date on each instrument to ensure that the calibration has not expired. *If calibration has expired, go to paragraph 5.4 below.*

5.2.4 Check instrument for satisfactory physical condition. If excessive dents, torn Mylar or loose parts are found, place the instrument out of service.

5.2.5 Perform a battery check and record the results on Attachment 1.

**5.2.5.1            Replace the batteries if they are low.**



5.2.5.2        *If the batteries are dead, take the instrument "out of service".*

5.2.6    Perform a source check and record the results in the appropriate columns on Attachment 1.

NOTE

The instrument must indicate within  $\pm 20\%$  of the expected response (*source activity*) listed on Attachment 1.

NOTE

The 43-20 alpha gas probes are interchangeable with the LM-12 count ratemeters. Periodic field checks of the instrument using the source attached to the instrument are required to verify continuing operability. Should the field check indicate no response or a reduced response, return the instrument to determine if the probe requires replacement or the if instrument requires repair.

5.2.7    Source check each quadrant of the Ludlum Model 43-20 alpha probe and record the results in the appropriate column.

5.2.8    Average the four quadrant reading and record this value on Attachment 1.

5.2.9    Record your initials next to each instrument checked on Attachment 1.

5.2.10   If an instrument is *found to be inoperable*, note on Attachment 1 why it is *being placed out of* service (i.e. out of calibration, *damage* repair, etc.) *and go to 5.4 below.*

5.3    **Beta Gamma Instruments:**

5.3.1    Select the desired instruments.

5.3.2    Record the current date and time on Attachment 1.

- 5.3.3 Check the calibration due date on each instrument to ensure that the calibration has not expired. *If calibration has expired, go to paragraph 5.4 below.*
- 5.3.4 Check instrument for satisfactory physical condition. If excessive dents, broken windows, or loose parts are found, place the instrument out of service.
- 5.3.5 Perform a battery check, and record the results on Attachment 1.
- 5.3.5.1 *Replace the batteries if they are low.*
- 5.3.5.2 *If the batteries are dead, take the instrument "out of service".*
- 5.3.6 Perform a *source* check with a Cs-137 source and record the results on Attachment 1.

NOTE

Reference readings shall be obtained on each instrument when exposed to a check source in a constant and reproducible manner at the time of, or promptly after, *instrument* calibration.

- 5.3.7 Record your initials next to each instrument checked on Attachment 1.
- 5.3.8 *If an instrument is found to be inoperable, note on Attachment 1 why it is being placed out of service (i.e. out of calibration, damage repair, etc.) and go to 5.4 below.*

#### 5.4 INSTRUMENT OUT OF CALIBRATION

- 5.4.1 When a instrument is found to be "out of calibration" or fails *an operability* check, immediately notify the HP Supervisor.
- 5.4.2 Source check failures ("out of calibration") are to be recorded in the instrument log book and a nonconformance report (NCR) shall be initiated per QPM-DOC #9, in order to *document the necessary corrective action(s) and to allow for management to* assess trends. *NCR's are not initiated for*

*instruments found with expired calibration due dates, and have not been used.*

- 5.4.3 The HP Supervisor shall determine the last date that the *used* instrument passed a *source check*, or the last calibration date, whichever is *most recent*.
- 5.4.4 Based on the last acceptable *source check or calibration* date, the HP Supervisor shall *identify which* radiological surveys were performed *since then* with the defective instrument.
- 5.4.5 The HP Supervisor shall determine whether regulatory or general information surveys were performed with the defective instrument.
- 5.4.6 Using previous surveys or previous knowledge of the survey data, the HP Supervisor shall determine whether the surveys taken with the defective *instrument* are acceptable *"as is"* or *whether* the surveys must be reperformed. In the case of regulatory surveys, *they* shall be retaken, if possible. *If* resurveying is not possible, the HP Supervisor will make a written assessment *as to* the quality of the data. *This assessment may also be used to disposition the NCR.*

## 6.0 RECORDS/REPORTS/NOTIFICATIONS

- 6.1 *Notifications required by the procedure will typically be verbal to the H. P. Supervisor.*
- 6.2 Forward the completed Attachment 1 forms to Health Physics Supervision for review.
- 6.3 Any instruments that have *dead batteries or* failed *the* source checks have been removed from service *and so noted on Attachment 1 and instrument log book.*
- 6.4 *Forward the dispositioned NCR to the Site manager for review and project filing.*

## 7.0 ATTACHMENTS

- 7.1 Attachment 1                      Portable Instrument Accountability Form (Example)

**DAILY PORTABLE INSTRUMENT CHECK**-WEST CHICAGO FACILITY

DATE

TIME

A.M.

P.M.

## ALPHA SURVEY INSTRUMENTS

## STANDARD S/N

INSTRUMENT TYPE AND SERIAL NO.	SOURCE ACTIVITY	INSTRUMENT RESPONSE	SOURCE ACTIVITY	INSTRUMENT RESPONSE	BATTERY CHECK	REMARKS	INITIALS
PAC-4G w/AC-21 PROBE 1505							
3986							
3992							
4015							
4022							
4044							
4058							
4177							
4178							
6057-02							
6057-03							
6057-04							
6057-05							

DATE

TIME

A.M.

**DAILY PORTABLE INSTRUMENT CHECK - WEST CHICAGO FACILITY**

P.M.

ALPHA SURVEY INSTRUMENTS

STANDARD S/N

INSTRUMENT TYPE AND SERIAL NO.	SOURCE ACTIVITY	INSTRUMENT RESPONSE	SOURCE ACTIVITY	INSTRUMENT RESPONSE	BATTERY CHECK	REMARKS				INITIALS
PRM-6 w/AC-3 PROBE 647										
653										
736										
765										
779										
1259										
Ludlum 43-20 Alpha Detector w/LM-12 Instrument		Average Response		Average Response		Indicate quadrant and response				
Inst. Number						1	2	3	4	

## ALPHA SURVEY INSTRUMENTS

[illegible]

**DAILY PORTABLE INSTRUMENT CHECK - WEST CHICAGO FACILITY**

DATE

TIME

A.M.

P.M.

BETA-GAMMA INSTRUMENTS

STANDARD S/N

INSTRUMENT TYPE AND SERIAL NO.	PROBE USED	BATTERY CHECK	HIGH VOLTAGE CHECK	RESPONSE CHECK	REMARKS	INITIALS
PRM-6 648	HP-210					
1263	HP-210					
1270	HP-210					
E-530 410	HP-270					
1133	HP-270					
1180	HP-270					
PRM-7 364	NaI					
699	NaI					
704	NaI					
707	NaI					
H.P.I. 1010 345	IC					

**DAILY PORTABLE INSTRUMENT CHECK - WEST CHICAGO FACILITY**

DATE

TIME

AM.

P.M.

**BETA-GAMMA INSTRUMENTS****STANDARD S/N**

<b>INSTRUMENT TYPE AND SERIAL NO.</b>	<b>PROBE USED</b>	<b>BATTERY CHECK</b>	<b>HIGH VOLTAGE CHECK</b>	<b>RESPONSE CHECK</b>	<b>REMARKS</b>	<b>INITIALS</b>
<b>LUDLUM MODEL 3 113990</b>	<b>44-40</b>					
<b>115345</b>	<b>44-40</b>					
<b>115385</b>	<b>44-40</b>					
<b>115025</b>	<b>44-40</b>					
<b>LUDLUM MODEL 3 114947</b>	<b>44-38</b>					
<b>115046</b>	<b>44-38</b>					
<b>115065</b>	<b>44-38</b>					
<b>115117</b>	<b>44-38</b>					
<b>115375</b>	<b>44-38</b>					



# **CALIBRATION OF THE LUDLUM SCALER RATEMETER MODEL 2221**

## **1.0 SCOPE**

### **1.1 Purpose**

To provide a standard procedure for the calibration of the Ludlum Ratemeter, model 2221 with the 44-10, 44-62 sodium iodide scintillation probes.

The 2221 is a portable, battery operated, self contained counting instrument designed for operation with scintillation, proportional or G-M detectors. When combined with scintillation detectors, the 2221 is used for the detection and measurement of gamma radiation. This instrument is used for down hole gamma logging as well as the detection of surface radioactivity.

### **1.2 Applicability**

This instrument will be calibrated every twelve months, after repairs, or when the instrument readings are questionable. This procedure can be used with any ratemeter/sodium iodide scintillation detector combination. Typically the 44-62 half-inch detector is not used for surface scanning.

## **2.0 REFERENCES**

- 2.1 32 Illinois Administrative Code, Parts 310 and 340, Standards for Protection Against Radiation
- 2.2 32 Illinois Administrative Code, Part 400, Notices, Instructions and Reports to Workers; Inspections
- 2.3 West Chicago Project, Health and Safety Plan Kerr-McGee Chemical Corporation
- 2.4 Technical Manual for Scaler Ratemeter, Model 2221
- 2.5 Kerr-McGee calibration standard blocks manufactured by K-M Technology and Engineering Report TR-94013
- 2.6 Calibration Drum Data 12 July 1995 and Calibration Drum Data from Sewage

## Treatment Plant Report

### 3.0 DEFINITIONS

N/A

### 4.0 REQUIREMENTS

#### 4.1 Prerequisites

None.

#### 4.2 Tools, Material, Equipment

4.2.1 Small screwdriver.

4.2.2 Ludlum Model 500 pulser or equivalent.

4.2.3 Certified, NIST-traceable source of sufficient activity to allow a response check.

#### 4.3 Precautions, Limit .

4.3.1 The connector cord is easily damaged if the weight of the 44-10 detector is suspended with it.

4.3.2 Do not leave the reading lamp on for any length of time as it will rapidly drain the battery voltage.

#### 4.4 Acceptance Criteria

The instrument response to the certified calibration source should be within  $\pm 20\%$  in order to be acceptable.

### 5.0 PROCEDURE

#### 5.1 Generic calibration applicable to all detectors.

NOTE: Calibrations for Surface activity and downhole logging are detailed in section 5.2.

5.1.1 Check the battery condition by pressing the "BAT" button with instrument switched on. If the meter does not indicate the battery charge above 5.3

volts, replace the four (4) D-cell batteries.

5.1.2 Set the threshold value as follows:

5.1.2.1 With the instrument turned on, press the threshold button. Read the displayed reading, if necessary adjust the **"THR"** adjustment screw until the threshold reads **100**.

**NOTE:** The **"THR"** adjustment screw is located under the calibration cover.

5.1.3 Set the window value as follows:

5.1.3.1 With the instrument turned on press the **"WIN"** button and observe the reading, if the reading does not indicate approximately **3830** then with the "win button depressed adjust the reading to 3830.

**NOTE:** The **"WIN"** adjustment screw is located under the calibration cover

5.2 SPECIFIC USE CALIBRATION

5.2.1 Surface Soil concentration Calibration

5.2.1.1 Use attachment 1 for calibration if the instrument is to be used for surface surveying.

5.2.2 Downhole logging

5.2.2.1 If instrument is to be used for downhole logging then proceed to attachment 2 for the calibration procedure.

6.0 RECORDS/REPORTS/NOTIFICATIONS

6.1 Instrument is properly calibrated and available for use or it has been placed out of service for repair.

6.2 Attachments have been reviewed and filed.

6.3 The equipment history has been updated.

7.0 ATTACHMENTS

7.1 Attachment 1 Soil Concentration Calibration Instructions

7.2	Attachment 2	Downhole Logging Calibration Instructions
7.3	Attachment 3	Soil Concentration Calibration Form
7.4	Attachment 4	Calibration Sticker
7.5	Attachment 5	Downhole logging Calibration Data Form

# Attachment 1

## CALIBRATION OF 2221 WITH 44-10 FOR SURFACE SCANNING

### WORK INSTRUCTION

1. Record the instrument and detector serial numbers on attachment 3.
2. Perform a scaler linear check as follows:
  - 2.1 Record the pulser model/serial number on attachment 3
  - 2.2 Record the calibration due date on attachment 3
  - 2.3 Check the threshold setting to insure that it is set at 100mv, if it is not set at 100mv then adjust it in accordance with section 5.
  - 2.4 Connect the pulser to the instrument.
  - 2.5 Send 400,4000.40K and 400K cpm pulses into the meter
  - 2.6 Record the meter responses in the "AS FOUND" column of attachment 3.
  - 2.7 If the meter does not indicate the correct response to within  $\pm 10\%$  perform the following steps as necessary:
    - 2.7.1 Send 400 cpm pulses into the meter and adjust the reading for an acceptable reading
    - 2.7.2 Send 4000 cpm pulses into the meter and adjust the reading for an acceptable reading
    - 2.7.3 Send 40k cpm pulses into the meter and adjust the reading for an acceptable reading
    - 2.7.4 Send 400k cpm pulses into the meter and adjust the reading for an acceptable reading
    - 2.7.5 Record the resulting readings in the after adjustment column on attachment 3
    - 2.7.6 If unable to adjust to within  $\pm 10\%$ , place the instrument out of service for repair.

### 1.3 PERFORM A VOLTAGE AND BACKGROUND AS FOLLOWS:

- 1.3.1 Record the source isotope and serial number on attachment 3.
- 1.3.2 Perform a source plateau by exposing the detector to a radioactive source and recording the meter reading at 50 volt increases until a plateau is developed. record the voltage and the meter reading for each increment on attachment 3.
- 1.3.3 At selected voltage increments perform a background reading and record the meter reading on attachment 3 .
  - 1.3.3.1 Set the meter high voltage to between 1/3 and 1/2 of the voltage plateau.
  - 1.3.3.2 Record the selected high voltage setting on attachment 3.

### 1.4 INSTRUMENT BACKGROUND

- 1.4.1 Perform an instrument **background** as follows:
  - 1.4.1.1 Using the four background blocks, perform six - one minute counts (with the instrument set at the selected voltage) and set in the scaler mode.
  - 1.4.1.2 Record these readings on attachment 3
  - 1.4.1.3 Average the six readings and record the result on attachment 3.

### 1.5 CALIBRATION SOURCE BLOCK DATA

- 1.5.1 Record the source block serial number on attachment 3
- 1.5.2 Perform six one minute source block counts
- 1.5.3 Record the results on attachment 3
- 1.5.4 Average the source block cpm and record the result on attachment 3
- 1.5.5 Subtract the average background (recorded on attachment 3) from the average source block cpm .
- 1.5.6 Record this number as the net average on attachment 3.

## 1.6 ACTIVITY CALCULATION

- 1.6.1 Perform the calculation on attachment 3 to determine the activity cutoff value for 7.2 pCi/g.
- 1.6.2 Sign attachment 3

## 1.7 CALIBRATION STICKER

- 1.7.1 Complete the information required on attachment 4 and attach it to the side of the instrument.

## Attachment 2

### CALIBRATION OF 2221 FOR GAMMA DOWNHOLE LOGGING

#### WORK INSTRUCTION

1. Record the instrument and detector serial numbers on attachment 3.
2. Perform a scaler linear check as follows:
  - 2.1 Record the pulser model/serial number on attachment 3
  - 2.2 Record the calibration due date on attachment 3
  - 2.3 Check the threshold setting to insure that it is set at 100mv, if it is not set at 100mv then adjust it in accordance with section 5.
  - 2.4 Connect the pulser to the instrument.
  - 2.5 Send 400,4000.40K and 400K cpm pulses into the meter
  - 2.6 Record the meter responses in the "AS FOUND" column of attachment 4.
  - 2.7 If the meter does not indicate the correct response to within  $\pm 10\%$  perform the following steps as necessary:
    - 2.7.1 Send 400 cpm pulses into the meter and adjust the reading for an acceptable reading
    - 2.7.2 Send 4000 cpm pulses into the meter and adjust the reading for an acceptable reading
    - 2.7.3 Send 40k cpm pulses into the meter and adjust the reading for an acceptable reading
    - 2.7.4 Send 400k cpm pulses into the meter and adjust the reading for an acceptable reading
    - 2.7.5 Record the resulting readings in the after adjustment column on attachment 3
    - 2.7.6 If unable to adjust to within  $\pm 10\%$ , place the instrument out of service for repair.

#### 1.3 PERFORM A VOLTAGE AND BACKGROUND AS FOLLOWS:

- 1.3.1 Record the source isotope and serial number on attachment 3.
- 1.3.2 Perform a source plateau by exposing the detector to a radioactive source and recording the meter reading at 50 volt increases until a plateau is developed. record the voltage and the meter reading for each increment on attachment 4.
- 1.3.3 At selected voltage increments perform a background reading and record the meter reading on attachment 3 .
  - 1.3.3.1 Set the meter high voltage to between 1/3 and 1/2 of the voltage plateau.
  - 1.3.3.2 Record the selected high voltage setting on attachment 3.

#### 1.4 INSTRUMENT BACKGROUND

- 1.4.1 Perform an instrument **background** as follows:
  - 1.4.1.1 Using the four background blocks, perform six-one minute counts (with the instrument set at the selected voltage) and set in the scaler mode.
  - 1.4.1.2 Record these readings on attachment 3
  - 1.4.1.3 Average the six readings and record the result on attachment 3.

#### 1.5 CALIBRATION SOURCE BLOCK DATA

- 1.5.1 Record the source block serial number on attachment 3
- 1.5.2 Perform six one minute source block counts
- 1.5.3 Record the results on attachment 3
- 1.5.4 Average the source block cpm and record the result on attachment 3
- 1.5.5 Subtract the average background (recorded on attachment 3) from the average source block cpm .

1.5.6 Record this number as the net average on attachment 3.

#### 1.6 ACTIVITY CALCULATION

1.6.1 Perform the calculation on attachment 3 to determine the activity cutoff value for 7.2 pCi/g.

1.6.2 Sign attachment 3

#### 1.7 CALIBRATION STICKER

1.7.1 Complete the information required on attachment 4 and attach it to the side of the instrument.

#### 1.8 DRUM CALIBRATION PROCEDURE

1.8.1 If the instrument and detector is also going to be used as a downhole Gamma logger the following calibration must also be performed.

1.8.1 After the instrument and detector have been calibrated for surface scanning, perform the following.

1.8.1.1 Connect the detector and the instrument with a 15 foot connecting cable.

1.8.1.2 Record the standard picocuries per gram for each calibration drum and record them on attachment 5

**1.8.1.3 Calibration Geometry must be the same as the Field Geometry, i.e. obtain a sample of the geoprobe steel pipe and insert it into the PVC calibration drums and place the down hole probe inside the geoprobe pipe.**

1.8.1.4 Take three one minute readings in each of the calibration drums located at the REF, and record the reading in the appropriate column on attachment 5

1.8.1.5 Average the each three one minutes and record the result on attachment 5

#### 1.9 ACTIVITY CALCULATION FOR WELL LOGGING

1.9.1 Perform a linear regression for the average readings for both the calibration drums equipped with steel augers as well as the PVC piping

1.9.2 Record the result on attachment 5

1.9.3 Calculate the activity for 5 pCi/g and & 7.2 pCi/g and record the results on attachment 5

1.9.4 Sign Attachment 5 and forward it for approval

#### 1.10 CALIBRATION STICKER

1.10.1 Complete the information required on attachment 4 and attach it to the side of the instrument.



**Ludlum Model 2221/44-10 Calibration**

page 1 of 2

Model 2221 serial number: \_\_\_\_\_

Probe 44-10 serial number: \_\_\_\_\_

Date: \_\_\_\_\_

**Scaler Linear Check**

Pulser model/serial number: \_\_\_\_\_ / \_\_\_\_\_

Calibration Due Date: \_\_\_\_\_

Threshold set to 100 mv. \_\_\_\_\_ (tech. init.)

Pulser setting in cts.	Multiplier	As Found Scaler reading in cts.	After Adjustment Scaler reading in cts.
_____	X1	_____	_____
_____	X10	_____	_____
_____	X100	_____	_____
_____	X1000	_____	_____

**Voltage Plateau**

Source isotope/serial number: \_\_\_\_\_ / \_\_\_\_\_

**BKGD PLATEAU****SOURCE PLATEAU**

volts	counts	volts	counts
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

operating voltage selected: \_\_\_\_\_

**Ludlum Model 2221/44-10 Calibration**

page 2 of 2

Model 2221 serial number: \_\_\_\_\_

Probe 44-10 serial number: \_\_\_\_\_

Date: \_\_\_\_\_ ☐ window verified at about 3830**Instrument BKGD****1 minute BKDG counts**

_____	_____
_____	_____
_____	_____

Average: \_\_\_\_\_

**Source Block Data****1 minute Source Block counts**

Source block ID: \_\_\_\_\_

_____	_____
_____	_____
_____	_____

Average: \_\_\_\_\_ cpm      Net Average: \_\_\_\_\_ cpm

**Activity Calculation**

Net Average source count rate of: \_\_\_\_\_ cpm      divided by 10 = \_\_\_\_\_

Times 7.2 = \_\_\_\_\_ (A)

Square root of (A) = \_\_\_\_\_ times 2 = \_\_\_\_\_ (B)

(A) plus the average BKGD = \_\_\_\_\_ CPM/7.2 pCi

The cutoff value is: \_\_\_\_\_ (CPM/7.2 pCi minus (B))

Calibration performed by: \_\_\_\_\_ DATE: \_\_\_\_\_

Calibration approved by: \_\_\_\_\_ DATE: \_\_\_\_\_

**ATTACHMENT 4  
CALIBRATION STICKER**

<b>SCALER #</b> _____	<b>PROBE #</b> _____	<b>Check</b> <u><b>Applicable Line</b></u>  Geoprobe Pipe _____ PVC Drum _____ Auger Drum _____ Cable Length _____
<b>CAL DATE</b> _____	<b>TECHNICIAN</b> _____	
<b>CAL DUE</b> _____	<b>VOLTAGE SETTING</b> _____	
<b>7.2 pCi/g =</b> _____ <b>CPM</b> <b>SOIL CONCENTRATION</b> _____ <b>DOWNHOLE LOGGING</b> _____		

<b>SCALER #</b> _____	<b>PROBE #</b> _____	<b>Check</b> <u><b>Applicable Line</b></u>  Geoprobe Pipe _____ PVC Drum _____ Auger Drum _____ Cable Length _____
<b>CAL DATE</b> _____	<b>TECHNICIAN</b> _____	
<b>CAL DUE</b> _____	<b>VOLTAGE SETTING</b> _____	
<b>7.2 pCi/g =</b> _____ <b>CPM</b> <b>SOIL CONCENTRATION</b> _____ <b>DOWNHOLE LOGGING</b> _____		

<b>SCALER #</b> _____	<b>PROBE #</b> _____	<b>Check</b> <u><b>Applicable Line</b></u>  Geoprobe Pipe _____ PVC Drum _____ Auger Drum _____ Cable Length _____
<b>CAL DATE</b> _____	<b>TECHNICIAN</b> _____	
<b>CAL DUE</b> _____	<b>VOLTAGE SETTING</b> _____	
<b>7.2 pCi/g =</b> _____ <b>CPM</b> <b>SOIL CONCENTRATION</b> _____ <b>DOWNHOLE LOGGING</b> _____		

<b>SCALER #</b> _____	<b>PROBE #</b> _____	<b>Check</b> <u><b>Applicable Line</b></u>  Geoprobe Pipe _____ PVC Drum _____ Auger Drum _____ Cable Length _____
<b>CAL DATE</b> _____	<b>TECHNICIAN</b> _____	
<b>CAL DUE</b> _____	<b>VOLTAGE SETTING</b> _____	
<b>7.2 pCi/g =</b> _____ <b>CPM</b> <b>SOIL CONCENTRATION</b> _____ <b>DOWNHOLE LOGGING</b> _____		

<b>SCALER #</b> _____	<b>PROBE #</b> _____	<b>Check</b> <u><b>Applicable Line</b></u>  Geoprobe Pipe _____ PVC Drum _____ Auger Drum _____ Cable Length _____
<b>CAL DATE</b> _____	<b>TECHNICIAN</b> _____	
<b>CAL DUE</b> _____	<b>VOLTAGE SETTING</b> _____	
<b>7.2 pCi/g =</b> _____ <b>CPM</b> <b>SOIL CONCENTRATION</b> _____ <b>DOWNHOLE LOGGING</b> _____		

<b>SCALER #</b> _____	<b>PROBE #</b> _____	<b>Check</b> <u><b>Applicable Line</b></u>  Geoprobe Pipe _____ PVC Drum _____ Auger Drum _____ Cable Length _____
<b>CAL DATE</b> _____	<b>TECHNICIAN</b> _____	
<b>CAL DUE</b> _____	<b>VOLTAGE SETTING</b> _____	
<b>7.2 pCi/g =</b> _____ <b>CPM</b> <b>SOIL CONCENTRATION</b> _____ <b>DOWNHOLE LOGGING</b> _____		

**ATTACHMENT 5  
DETECTOR CALCULATION**

DETECTOR TYPE \_\_\_\_\_ SER # \_\_\_\_\_

**CALIBRATION DRUMS W/PVC PIPING:** CABLE LENGTH \_\_\_\_\_ DIAMETER OF PIPE \_\_\_\_\_ SCH. OF PIPE 40, 80

DRUM NUMBER	pCi/g	1ST COUNT ( cpm )	2ND COUNT( cpm )	3RD COUNT( cpm )	AVERAGE COUNT
CD-1	1.7				
CD-8	12.9				
CD-7	23.4				

LINEAR REGRESSION FORMULA  $Y = A + BX$  WHERE Y= CPM AND X= pCi/g

A= \_\_\_\_\_ R= \_\_\_\_\_ 5.0 pCi/g = \_\_\_\_\_ CPM

B= \_\_\_\_\_ 7.2 pCi/g = \_\_\_\_\_ CPM

**CALIBRATION W/STEEL HOLLOW STEM AUGER PIPING:** CABLE LENGTH \_\_\_\_\_ DIAMETER OF PIPE \_\_\_\_\_ SCH. OF PIPE 40, 80

DRUM NUMBER	pCi/g	1ST COUNT( cpm )	2ND COUNT( cpm )	3RD COUNT( cpm )	AVERAGE COUNT
10	2.4				
12	5.8				
13	22.4				

LINEAR REGRESSION FORMULA  $Y = A + BX$  WHERE Y= CPM AND X= pCi/g

A= \_\_\_\_\_ R= \_\_\_\_\_ 5.0 pCi/g = \_\_\_\_\_ CPM

B= \_\_\_\_\_ 7.2 pCi/g = \_\_\_\_\_ CPM

**CALIBR. DRUMS W/PVC & GEOPROBE STEEL PIPING:** CABLE LENGTH \_\_\_\_\_ DIAMETER OF PIPE \_\_\_\_\_ SCH. OF PIPE 40, 80

DRUM NUMBER	pCi/g	1ST COUNT( cpm )	2ND COUNT( cpm )	3RD COUNT( cpm )	AVERAGE COUNT
CD-1	1.7				
CD-8	12.9				
CD-7	23.4				

LINEAR REGRESSION FORMULA  $Y = A + BX$  WHERE Y= CPM AND X= pCi/g

A= \_\_\_\_\_ R= \_\_\_\_\_ 5.0 pCi/g = \_\_\_\_\_ CPM

B= \_\_\_\_\_ 7.2 pCi/g = \_\_\_\_\_ CPM